



Product Change Notification

TE Connectivity

Product Change Notification: P-19-017665

PCN Date: 24-JUL-19

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Manufacturing Location Change Appliances Tubing XFFR Products

Description of Changes

Manufacturing location change. Following Part Numbers will be transferred from Menlo Park, USA to Trutnov, CZ. TE Connectivity is continuing to move production of XFFR tubing to Trutnov CZ Republic. This on-going transfer is being made in phases until all appropriate equipment has moved. Different parts will move in different phases. We will start to ship XFFR products from the Czech Republic after September 6th 2019. After this date TE reserves the right to provide qualified products from any of the manufacturing locations during this transfer until the final closure date of Menlo Park location by the end of 2019. As not all part numbers will transfer at the same time customers may still receive Products from the Menlo Park location after this transfer date due to inventory. Where necessary TE will continue with internal qualification and testing of products after they are received at the new locations.

Other attachments:

- [PCN XFFR Packaging file](#)
- [PCN XFFR Product Notification](#)
- [PCN XFFR Packaging file](#)
- [PCN XFFR Product Notification](#)
- [PCN XFFR Packaging file](#)
- [PCN XFFR Product Notification](#)

Reason for Changes:

Dear Customer, we hereby inform you about a transfer of processes. The transfer follows a strict procedure, which fully maintains quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location operates under a certified quality management system in accordance with standard automotive requirements. A TE-internal release test based on the relevant part specifications will be executed before delivery. If you require PPAP or specific testing please inform us within 90 days of receiving this notification, so we can coordinate the documentation and support your requirements. Should samples be required, a limited range of product is available. After this 90 day period we will begin the transfer. TE will take no reply as customers being satisfied with the TE internal qualification and testing. The release specifications for these products have not changed and part numbers for the spooled products and cut pieces remain the same.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	06-SEP-2019
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	31-DEC-2019

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
CB5430-000	NO			"XFFR-03X4", "5-1899230-5"			
CB5431-000	NO			"6-1899220-7", "XFFR-04X25"			
CB5432-000	NO			"XFFR-04X4", "5-1899230-7"			
CB5435-000	NO			"XFFR-07X4", "1899235-9"			
CB5437-000	NO			"XFFR-11X4", "5-1899230-8"			
CB5440-000	NO			"XFFR-15X4", "6-1899230-0"			
CB5443-000	NO			"2-1899833-5"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
CB5430-000	NO			"XFFR-03X4", "5-1899230-5"			
CB5431-000	NO			"6-1899220-7", "XFFR-04X25"			
CB5432-000	NO			"XFFR-04X4", "5-1899230-7"			
CB5435-000	NO			"XFFR-07X4", "1899235-9"			
CB5437-000	NO			"XFFR-11X4", "5-1899230-8"			
CB5440-000	NO			"XFFR-15X4", "6-1899230-0"			
CB5443-000	NO			"2-1899833-5"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
CB5430-000	NO			"XFFR-03X4", "5-1899230-5"			
CB5432-000	NO			"XFFR-04X4", "5-1899230-7"			
CB5435-000	NO			"XFFR-07X4", "1899235-9"			
CB5437-000	NO			"XFFR-11X4", "5-1899230-8"			
CB5440-000	NO			"XFFR-15X4", "6-1899230-0"			
CB5443-000	NO			"2-1899833-5"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
CB5430-000	NO			"XFFR-03X4", "5-1899230-5"			
CB5431-000	NO			"6-1899220-7", "XFFR-04X25"			
CB5432-000	NO			"XFFR-04X4", "5-1899230-7"			
CB5435-000	NO			"XFFR-07X4", "1899235-9"			
CB5437-000	NO			"XFFR-11X4", "5-1899230-8"			
CB5440-000	NO			"XFFR-15X4", "6-1899230-0"			
CB5443-000	NO			"2-1899833-5"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
CB5430-000	NO			"XFFR-03X4", "5-1899230-5"			
CB5432-000	NO			"XFFR-04X4", "5-1899230-7"			
CB5435-000	NO			"XFFR-07X4", "1899235-9"			
CB5437-000	NO			"XFFR-11X4", "5-1899230-8"			
CB5440-000	NO			"XFFR-15X4", "6-1899230-0"			
CB5443-000	NO			"2-1899833-5"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
CB5430-000	NO			"XFFR-03X4", "5-1899230-5"			
CB5432-000	NO			"XFFR-04X4", "5-1899230-7"			
CB5435-000	NO			"XFFR-07X4", "1899235-9"			
CB5437-000	NO			"XFFR-11X4", "5-1899230-8"			
CB5440-000	NO			"XFFR-15X4", "6-1899230-0"			
CB5443-000	NO			"2-1899833-5"			