

Product Discontinuation Notice


February 2012

Discontinuation of Plug-In Sockets and DIN Rail Terminal Sockets



1. Reason: Low market demand

2. Affected parts:

| | | |
|--|-----------|----------------------|
| <p>Plug-in sockets and DIN rail terminal sockets</p>  | All types | HG2- HG3- HG4- |
|--|-----------|----------------------|

3. Last time buy: End of August 2012

4. Substitution: None

Any questions, please contact your local Panasonic Electric Works Sales representatives.

(Ref#: T-1246-10)