

Product Change Notification



Product Group: Vishay Dale/July 2, 2018/PCN-DI-00407-2018 Rev 0

EB62 Product Obsolescence

DESCRIPTION OF CHANGE: The Vishay EB62 connector series is going to End of Life.

CLASSIFICATION OF CHANGE: Product Obsolescence

REASON FOR CHANGE: Improved molding material available.

EXPECTED INFLUENCE ON QUALITY/RELIABILTY/PERFORMANCE: None. Vishay will provide

alternate mold material. Replace EB62 with EB63 when ordering.

Current Material (Glass-filled Phenolic per MIL-M-14, green)	Alternate Material (Thermoplastic Polyester, glass filled, black)
EB62	EB63

PRODUCT CATAGORY: Connectors

PART NUMBERS/SERIES/FAMILIES AFFECTED:

EB62-S0D2260W	EB62-S0D2860X	EB62-S0D3060W	EB62-S0D4460X
EB62-S0D5040X	EB62-S0D5040X-6	EB62-S0D5060X	EB62-S0K186FS
EB62-S0K306FS	EB62-S0K4040X	EB62-S0K4060X	EB62-S2R2860X

VISHAY BRAND(s): Vishay Dale

TIME SCHEDULE:

Start Shipment Date: N/A

Last Time Buy Date: 12/31/2018 Last Time Shipment Date: 2/28/2019

SAMPLE AVAILABILITY: N/A

PRODUCT IDENTIFICATION: N/A

QUALIFICATION DATA: N/A

This PCN is considered approved, without further notification, unless we receive specific customer concerns or as specified by contract.

ISSUED BY: Doug Lillie, Sr. Product Marketing Manager

For further information, please contact your regional Vishay office.

CONTACT INFORMATION:

The Americas Vishay Intertechnology, Inc 1505 East Highway 50

P. O. Box 180

Yankton, South Dakota 57078

Ph: 1 605-665-9301 Fax: 1 605-665-1627 doug.lillie@vishay.com Europe

Vishay Electronic GmbH

Dr.-Felix-Zandman-Platz 1 95100 Selb

Germany

Ph: 49-9287-71-2282 Fax: 49-9287-71-2496 jens.walther@vishay.com Asia

Vishay Asia Pte Ltd. 25 Tampines Street 92 Keppel Building #02-00 Singapore 528877 Ph: +65-788-6668 Fax: +65-788-3383 victor.goh@vishay.com

Vishay Intertechnology, Inc.