



Phoenix Contact Inc.
 P.O. BOX 4100
 Harrisburg, PA 17111-0100
 Phone: 717-944-1300
 Fax: 717-944-1625

Product Discontinuation

PDN-ICC-1521-2018

Business Unit	Product Line Code	Type of Change	Action	Date of Issue
ICC - Industrial Cabinet	BE2	Product Discontinuation	Notify Distributors and Field	4/23/2018

Phoenix Contact's factory has announced the following product(s) is going to be discontinued. Existing specifications will be met or exceeded. Technical support of the discontinued product will continue, as required. Please review and acknowledge this document and take the appropriate action with respect to your existing inventory and ordering replacement parts.

Description for Product Discontinuation

Various articles are being discontinued as part of product lifecycle management. The discontinuation concerns parts without sales quantities/customer requirements as well as old articles that have since been replaced.

Stock Status

Can existing stock still be used?	Yes
Is mixture of stock acceptable?	Yes

Transaction Dates

Last Buy from Phoenix Contact:	7/31/2018
Last Scheduled Ship from Phoenix Contact:	10/31/2018

Should you have any issues with the timeline or content of this product discontinuation, please contact Phoenix Contact using the information below. Customers should acknowledge receipt of the PDN within 30 days of delivery of the PDN; provided, however, that the failure to acknowledge receipt does not affect the product discontinuation or the effective date thereof.

Contact Info:

Cory Myer
 cmyer@phoenixcon.com

Thank you,

Alan Sappe

Senior Specialist



Phoenix Contact Inc.
P.O. BOX 4100
Harrisburg, PA 17111-0100
Phone: 717-944-1300
Fax: 717-944-1625

Product Discontinuation

Discontinued Part #	Type Description	Replacement Part #	Type Description
3037850	ST 2,5-TWIN-DIO/R-L RD		
3031556	STTB 2,5-DIO 1N 5408K /O-U		
3039939	STTBS 2,5-LA 24 RD		
3029826	MZFKK 1,5-PV		
3005743	MZFK 1,5 BU		
3005714	MZFKKB 1,5		
3003473	MZFK 1,5-PE		
3029813	MZFKK 1,5		
3003758	MZFK 1,5		
3192038	RVS 10-TP(2,4X0,8)L		
3248212	MP 6X1,5 WH		
3248166	MP 8X1,5		
3248184	MP 10X1,5 BU		
3248168	MP 10X1,5		
3248180	MP 6X1,5 BU		
3248156	MP 1,5 WH		
2701569	GE 35/2-B		
2701573	GE 10/2-B BU		
3071082	GE 35/1		
3071065	GE 35/2		
3037614	STTB 2,5-DIO/O-U BK		
2701572	GE 10/2-B		
3076196	RBO 16-3L/N/FE-HC		
3076154	RBO 16-3L/FE-HC		
3076248	RBO 8-3L/N		
3076086	RBO 8-3L/N-HC		
3076251	RBO 10-3L/N		
3076137	RBO 10-3L/FE		
3076112	RBO 16-3L/N-HC		
3076222	RBO 12-3L		
3076219	RBO 10-3L		
3076125	RBO 8-3L/FE-HC		
3076138	RBO 10-3L/FE-HC		
3076073	RBO 16-3L-HC		
3076099	RBO 10-3L/N-HC		
3076206	RBO 8-3L		
3034060	DT 2,5-QUATTRO BU		
3034073	DT 2,5-QUATTRO-PE		
3034057	DT 2,5-QUATTRO		
3034028	DT 2,5		
3034086	DT 2,5-TWIN		
1960026	UKB 4-FS(2-2,8-0,8)		
1954443	UVKB 4-FS(4-2,8)TP(2,4X0,8)4L		
3006519	ZVIOK 1,5-LA 24GN/O-MO		
3076639	UKH 50-3L/N-F		
3076640	UKH 50-3L/FE-F		
3076638	UKH 50-3L-F		
3076633	UKH 240-3L/N/FE-F		
3076439	UKH 240-3L/FE		
3076641	UKH 50-3L/N/FE-F		



Phoenix Contact Inc.
P.O. BOX 4100
Harrisburg, PA 17111-0100
Phone: 717-944-1300
Fax: 717-944-1625

Product Discontinuation

3076636	UKH 50-3L/FE		
3076345	UKH 150-3L		
3076634	UKH 50-3L		
3116044	UK 5-R-C-1K		
2718112	VIOK 1,5-LA 24GN/O-MO		
2718170	VIOK 1,5-LA230GN/O-MO		
3026984	UKK 5-R 3,3K/O-U		
2717126	DOK 1,5-DIO-M-O		
3100103	MTKD-NICRSI/NISI EX		
2775359	UDK 4-ULA 24 GN/O-U		
3074240	UKKB 3 GN		
2791414	UKK 5-LA 24 GN/U-O		
2794482	UKK 5-2DIO/O-UL/O-UR		
2791333	UKK 5-LA 60 RD/U-O		
3073908	UKK 5 BK		
2791197	UKK 5-2DIO/O-UR/UL-UR		
2775032	UDK 4-ULA 48 RD/O-U		
3003871	MBKKB 2,5-2DIO/O-UL/O-UR		
2775045	UDK 4-ULA 24 RD/O-U		
2775058	UDK 4-ULA 230		
3064111	UT 2,5-MTD P/P BU		