



Product Change Notification

TE Connectivity

Product Change Notification: PCN-22-160311

PCN Date: 15-DEC-22

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description: (Text limited to 120 characters)
Heat shrink tube

Description of Changes
As part of an ongoing and regular cleanup activity TE has identified several unused part numbers sitting in the heat shrink tubing Global Product Line 715

Reason for Changes:

PCN Attributes:	
Product Category: Heat Shrink Tubing	Kind of Change: Status Change
Change Feature: Discontinuance	Potential Customer Impact:
Remarks:	

Estimated Dates:	
Last Order Date (Obsolete Parts Only): 16-DEC-2022	First Ship Date of Changed Items (Changed Parts Only):
Last Ship Date of Changed Items (Obsolete Parts Only): 16-DEC-2022	Last Date for Mixed Shipments: (Changed Parts Only): No Mixed Shipments
Effectivity Date:	Date of First Samples:

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
017309P001	YES		1-1190135-1, FP21-1/2-X-48IN			
041773-000	YES		1-1190320-2, VFP-1-0-FSP	NB14254001		PBL parts superseded by Standard part
043300-000	YES		5-1197931-1, RNF-100-3/8-CL-SP-CS7465			
098235M002	YES		3-1190719-1, FP21-1/8-9-SP			
1-603329-1	YES		"708083P002", "FP21-3/4-0-48IN"			
127459P001	YES		5-1190926-5, FP21-1/4-9-48IN			
150949M004	YES		3-1191091-8, VFP-21-3/64-0-SP-SM			
186504-000	YES		4-1199983-7, RNF-100-1/2R-BK-STK			
214347-000	YES		3-1191548-6, RNF-100-3/8-YO-SP-CS7554			

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2488794001	YES		2-1191825-7, RNF-100-3/16-BK-BULK-SP			
277107H001	YES		1-1192052-8, VFP-21-3/8-0-STK-SM			
277107M004	YES		2-1192052-2, VFP-21-3/8-0-SP-SM			
289569-000	YES		6-1192195-1, RNF-100-1/8-GN-SP-CS7554			
295547-000	YES		2-1192239-2, RNF-100-1/2-RD-SP-CS5006			
339249-000	YES		4-1192560-6, RNF-100-5/8-BK-SP			
340378-000	YES		6-1198798-4, RNF-100-1-YO-STK-CS7465			
346571N001	YES		9-1192608-9, FP21-1/4-9-SP			
375459P006	YES		7-1192812-9, VFP-21-1/4-9-48IN-SM			
377135J002	YES		2-1192824-5, VFP-21-1/8-0-SP-SM			
396017-000	YES		6-1192970-6, VFP-3/4-9-FSP	NB14444001		PBL parts superseded by Standard part
404829P001	YES		3-1193055-9, FP21-3/64-0-48IN			
408675-000	YES		7-1193082-0, RNF-100-1-RD-SP-CS7465			
442923-000	YES		4-1193329-9, RNF-100-1/4-RD-SP-CS7554			
4431674001	YES		2-1193331-5, VFP-1/2-9-FSP	NB14234001		PBL parts superseded by Standard part
459730-000	YES		1-1199022-2, RNF-100-3/64-WH-SP-CS5004			
480239-000	YES		2-1193595-1, VFP-3-0-SP	NB17804001		PBL parts superseded by Standard part
504570-000	YES		2-1199022-5, RNF-100-3/32-YO-SP-CS5004			
505284L054	YES		1193822-5, RNF-100-3/64-BKSTK-CS6162			
505290L035	YES		1-1193825-1, RNF-100-1/16-RD-STKCS5529			
505294M215	YES		3-1193828-2, RNF-100-3/32-BK-SP-CS5583			
505298L147	YES		3-1193832-0, RNF-100-3/32-WH-STKCS5004			
505299L168	YES		7-1193834-7, RNF-100-1/8-BK-STK-CS7250			
505306M080	YES		6-1193842-4, RNF-100-3/16-YO-SP-CS6162			

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
505309P431	YES		1-1193848-3, RNF-100-1/4-BK-2.5IN			
505313M118	YES		3-1193852-7, RNF-100-1/4-WH-SP-CS7375			
505313M224	YES		3-1193852-8, RNF-100-1/4-WHSPCS5004			
505314B374	YES		8-1193854-6, RNF-100-3/8-BK			
505314J376	YES		9-1193854-6, RNF-100-3/8-BK-SP-SM			
505314L377	YES		9-1193854-7, RNF-100-3/8-BK-STK-CS7224			
505314L546	YES		9-1193854-8, RNF-100-3/8-BK-STKCS5004			
505314M547	YES		1193855-1, RNF-100-3/8-BKSPCS5004			
505318M076	YES		5-1193861-2, RNF-100-3/8-WH-SP-CS5321			
5053196354	YES		4-1193863-3, RNF-100-1/2-BK-2IN			
505319M260	YES		9-1193863-3, RNF-100-1/2-BK-SP-CS6162			
505320L078	YES		7-1193865-1, RNF-100-1/2-RD-STK-CS5318			
505324M353	YES		7-1193870-6, RNF-100-3/4-BK-SP-CS5004			
505324P319	YES		6-1193871-7, RNF-100-3/4-BK-50MM			
505324P343	YES		7-1193871-3, RNF-100-3/4-A1-BK-55MM			
505326L134	YES		3-1193873-3, RNF-100-3/4-YO-STK-CS5529			
505329M253	YES		5-1193877-8, RNF-100-1-BK-SP-CS7387			
505332M029	YES		8-1193880-0, RNF-100-1-BU-SP-CS5529			
505333M212	YES		5-1193881-1, RNF-100-1-WH-SP-CS7465			
505338M052	YES		5-1193885-9, RNF-100-1-1/2-WH-SPCS5529			
505344L068	YES		1193888-3, RNF-100-3-BK-STKCS5004			
505349L026	YES		3-1193889-9, RNF-100-4-BK-STK-CS6162			
5053534026	YES		1193890-9, RNF-100-4-WH-SP			
5053942010	YES		7-1193891-5, RNF-100-3/64-BN-STK			
5053954012	YES		8-1193891-4, RNF-100-3/64-OR-SP			
5054114018	YES		2-1193894-4, RNF-100-3/16-OR-SP			

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5054212011	YES		1193896-3, RNF-100-1/2-OR-STK			
505424M023	YES		5-1193896-7, RNF-100-3/4-BN-SP-CS5321			
5054324010	YES		6-1193897-5, RNF-100-1-1/2-OR-SP			
505442M022	YES		2-1193899-0, RNF-100-1/8-GN-SP-CS5006			
505443M027	YES		6-1193899-9, RNF-100-3/8-GN-SP-CS5321			
5058634006	YES		2-1193905-9, RNF-100-1-1/4-RD-SP			
507005B054	YES		9-1193962-5, RNF-100-3/16-CL			
507005L055	YES		9-1193962-8, RNF-100-3/16-CL-STKCS5006			
507005M059	YES		1193963-1, RNF-100-3/16-CL-SP-CS5006			
507008M136	YES		2-1193966-9, RNF-100-1/2-CL-SP-CS6162			
507012L052	YES		9-1193969-7, RNF-100-2-CL-STK-CS7312			
507013M018	YES		3-1193970-2, RNF-100-3-CL-SP-CS5006			
5201946048	YES		2-1194087-4, RT-3-NO.3-0-1.25IN			
573229-000	YES		6-1194550-9, RNF-100-3/32-CL-SP-CS5868			
594727P006	YES		7-1194701-3, VFP-21-1/16-0-12IN-SM			
595885-000	YES		1194712-2, RNF-100-1/4-CL-STK-CS7312			
602185P002	YES		1194767-8, VFP-21-1/16-9-48IN-SM			
602941-000	YES		1-1197891-9, VFP-21-3-0-48IN-CS7661			
665491-000	YES		4-1195243-7, VFP-1-6-SP			
683239P003	YES		7-1195369-9, VFP-21-1/8-9-48IN-SM			
691461-000	YES		1195429-3, RNF-100-1/2-WH-STK-CS5551			
7655194002	YES		4-1195959-0, RNF-100-NO.322-BK-SP			
804093-000	YES		1197882-8, RNF-100-3/32-BU-SP-CS5004			
8159614002	YES		7-1196358-0, VFP-1/2-2-SP	NB14164001		PBL parts superseded by Standard part
819639M001	YES		4-1196387-7, FP21-1-1/2-0-SP			

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
824991J001	YES		1-1196442-4, HIX-VW1-1-0-SP-SM			
832204-000	YES		6-1199983-5, RNF-100-3/4R-BK-STK			
848323-000	YES		7-1196615-0, FP21-3/4-9-STK			
853963H003	YES		2-1196657-7, HIX-VW1-1/8-0-STK-SM			
875185J002	YES		3-1196808-1, HIX-VW1-1/2-0-SP-SM			
878771M002	YES		1-1196841-2, FP21-1/16-0-SP			
885125-000	YES		9-1196887-0, VFP-1-2-FSP	NB14304001		PBL parts superseded by Standard part
904565-000	YES		5-1197029-2, RNF-100-3/4-WH-SP-CS7554			
9053854002	YES		2-1197035-2, RNF-100-NO.301-CL-SP			
914696-000	YES		4-1198914-2, RNF-100-1-WH-SP-CS5004			
9162754001	YES		9-1197112-2, VFP-3/4-4-SP	NB15014001		PBL parts superseded by Standard part
935106-000	YES		7-1198832-6, VFP-21-1/8-0-4IN-SM			
9547154001	YES		1197392-1, VFP-1/2-0-SP	NB14134001		PBL parts superseded by Standard part
955297-000	YES		9-1197395-7, RNF-100-3/16-WH-SP-CS7554			
983781-000	YES		6-1197600-2, VFP-1/2-2-FSP	NB14154001		PBL parts superseded by Standard part
A09061-000	YES		1-1201492-1, RNF-100-4-BK-STK-CS5592			
A16446-000	YES		5-1201677-3, RNF-100-1/2-BK-SP-CS5004			
C28473-000	YES		1-1201734-9, RNF-100-1/4-CL-SP-CS7312			
C54502-000	YES		2-1201792-6, V4-TOKO-10.0-0-FSP-SM			
C95115-000	YES		6-1200398-0, TC-CAPS-4005-8-UNINSP			
CB2391-000	YES		RNF-100-1/2-BK-700MM			
CF4691-000	YES		RNF-100-1/2-RD-1.5IN			
CJ8165-000	YES		"RNF-100-1/2-RD-50MM", "5-1899833-1"			
CL0554-000	YES		"RNF-100-3/32-CL-SP-CS8764"			

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
CL4287-000	YES		"RNF-100-3/8-CL-STK-CS7250"			
CL6871-000	YES		"RNF-100-135/149-BK-SP-CS8779"			
CL8583-000	YES		"INSL-22893-RNF100-0.112-CL-STK"			
CM9026-000	YES		7-1899833-0, RNF-100-1/4-CL-2IN			
CN2757-000	YES		RNF-100-1/2-BK-STK-CS7387			
CN6197-000	YES					
CN7751-000	YES					
CN8831-000	YES					
CP1255-000	YES					
CP5733-000	YES		RNF-100-1-BK-95MM			
CP9849-000	YES					
CR3288-000	YES					
CR6327-000	YES		RNF-100-1/4-CL-30MM			
CR8361-000	YES		"5-1899816-9"			
CU1245-000	YES					
CU1870-000	YES					
CV4180-000	YES					
CV4197-000	YES					
CV4199-000	YES					
CV4200-000	YES					
CV4203-000	YES					
CV4207-000	YES					
CV4217-000	YES					
CW3543-000	YES		RNF-100-1-RD-30MM			
CX0799-000	YES		"RNF-100-1-CL-FSP-CS5868", "7-1899832-2"			
CZ7155-000	YES					
D13210-000	YES		5-1201735-4, RNF-100-3/16-BK-SP-CS7210			
D15678-000	YES		1199964-1, VERSAFIT-3/8-0-FSP-CS5430	NB23764001		Sales UOM change.
D22255-000	YES		8-1200481-8, RNF-100-1/16-BK-SP-CS7387			
D78511-000	YES		7-1201240-8, JN-MIL-LT-1/8-2-20MM			
D95475-000	YES		1-1201793-1, RNF-100-092/078-CL-SP			
E36334-000	YES		2-1202162-8, RNF-100-2-BK-STK-CS7250			
E95708-000	YES		8-1199962-6, RNF-100-3/8-BK-STK-CS7728			
EG0430-000	YES					
EG0542-000	YES		RNF-100-3/64-GY-STK			
EG7220-000	YES					
EG8035-000	YES					

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
EK0732-000	YES					
EK0733-000	YES					
EM1152-000	YES					
EM1155-000	YES					
EM1156-000	YES					
EM4881-000	YES		VERSAFIT-3/4-0-38MM			
EM5334-000	YES		VERSAFIT-3/8-0-5IN			
EP0790-000	YES					
EP6336-000	YES					
EP6337-000	YES					
EP6378-000	YES					
EP6387-000	YES					
EP7587-000	YES					
EP7590-000	YES					
EP8998-000	YES					
F26811-000	YES		5-1201666-6, RNF-100-1/2-BK-690MM			
F34682-000	YES		8-1201755-5, RNF-100-3/4-WH-STK-CS5592			
F36947-000	YES		5-1201769-9, RNF-100-3/64-WH-STKCS5321			
F40630-000	YES		5-1200482-7, RNF-100-1/2-WH-FSP-CS5004			
F44472-000	YES		9-1201717-0, RNF-100-1-CL-STK-CS7620			
F68207-000	YES		5-1201301-0, RNF-100-1-BK-SP-CS5004			