



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M001075I

DATE: 02-May-2022

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	DS1089LU-450+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	DS21Q50LN+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	DS2465Q+T	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	DS2465Q+U	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	DS28EL15X-S+T	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX1060BCEI+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX1060BCEI+T	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX1086C/D+C01063	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX1204ACAP+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX14535EEVB+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX14535EEVB+T	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX14741EVKIT#	N/A	02-May-2022	01-Nov-2023	EVKIT is No Longer Supported
Discontinuance	MAX15062C2.5EVKIT#	N/A	02-May-2022	01-Nov-2023	EVKIT is No Longer Supported
Discontinuance	MAX154ACWG+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX154ACWG+T	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX16060DTE+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX16060DTE+T	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX16924GTM/V+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX16924GTM/V+T	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX16935BAUER/V+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX16935BAUER/V+T	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX17079GTL+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX17079GTL+T	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX1846EVKIT+	N/A	02-May-2022	01-Nov-2023	EVKIT is No Longer Supported
Discontinuance	MAX19588EVKIT+	N/A	02-May-2022	01-Nov-2023	EVKIT is No Longer Supported
Discontinuance	MAX1976AETT150+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 02-Jun-2022

Discontinuance	MAX1976AETT150+T	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX1976AETT150/V+	N/A	02-May-2022	02-May-2022	The part was not released
Discontinuance	MAX1976AETT150/V+T	N/A	02-May-2022	02-May-2022	The part was not released
Discontinuance	MAX20044FGEEB/V+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX20044FGEEB/V+T	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX20072EVKIT#	N/A	02-May-2022	01-Nov-2023	EVKIT is No Longer Supported
Discontinuance	MAX20413ATGA/V+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX20413ATGA/V+T	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX2150EVKIT+	N/A	02-May-2022	01-Nov-2023	EVKIT is No Longer Supported
Discontinuance	MAX2171ETL+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX2171ETL+T	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX2673EVKIT+	N/A	02-May-2022	01-Nov-2023	EVKIT is No Longer Supported
Discontinuance	MAX2769BEVKIT#	N/A	02-May-2022	01-Nov-2023	EVKIT is No Longer Supported
Discontinuance	MAX2838ETM+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX2838ETM+T	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX2904ETI+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX3077EEPA+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX34461AA00EVKIT#	N/A	02-May-2022	01-Nov-2023	EVKIT is No Longer Supported
Discontinuance	MAX40003EVKIT#	N/A	02-May-2022	01-Nov-2023	EVKIT is No Longer Supported
Discontinuance	MAX40004EVKIT#	N/A	02-May-2022	01-Nov-2023	EVKIT is No Longer Supported
Discontinuance	MAX40005EVKIT#	N/A	02-May-2022	01-Nov-2023	EVKIT is No Longer Supported
Discontinuance	MAX4372EVKIT#	N/A	02-May-2022	01-Nov-2023	EVKIT is No Longer Supported
Discontinuance	MAX4434ESA+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX4434ESA+T	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX4969CTO+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX4969CTO+T	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX5027EUT+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX5027EUT+T	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX507AEWG+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX507AEWG+T	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX5944EVKIT	N/A	02-May-2022	01-Nov-2023	EVKIT is No Longer Supported
Discontinuance	MAX6319LHUK31A+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX6319LHUK31A+T	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX6382XR26D3+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX6382XR26D3+T	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX6390XS30D7+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 02-Jun-2022

Discontinuance	MAX6390XS30D7+T	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX6508UT8255+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX6508UT8255+T	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX6804US44D3+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX6804US44D3+T	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX6835VXSD0+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX6835VXSD0+T	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX6836VXSD3+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX6836VXSD3+T	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX6866UK17D3L+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX6866UK17D3L+T	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX693EJE	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX77825EWP+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX77825EWP+T	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX77826EVKIT#	N/A	02-May-2022	01-Nov-2023	EVKIT is No Longer Supported
Discontinuance	MAX8529EEG+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX8529EEG+T	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX863EVKIT	N/A	02-May-2022	01-Nov-2023	EVKIT is No Longer Supported
Discontinuance	MAX8643EVKIT+	N/A	02-May-2022	01-Nov-2023	EVKIT is No Longer Supported
Discontinuance	MAX8731AEVKIT+	N/A	02-May-2022	01-Nov-2023	EVKIT is No Longer Supported
Discontinuance	MAX8855EVKIT+	N/A	02-May-2022	01-Nov-2023	EVKIT is No Longer Supported
Discontinuance	MAX8895YEWA+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX8895YEWA+T	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX9395EHJ+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX9532AUB+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX9532AUB+T	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX9532AUB/V+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX9532AUB/V+T	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX98928EWX+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAX98928EWX+T	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAXQ613X-0000+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAXQ613X-2562+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAXQ613X-2573+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAXQ613X-2592+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
Discontinuance	MAXREFDES77#	N/A	02-May-2022	01-Nov-2023	EVKIT is No Longer Supported
Discontinuance	MX7225LCWG+	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 02-Jun-2022

Discontinuance	VT253FQX-ADJ	N/A	02-May-2022	01-Nov-2023	Part can no longer be manufactured
----------------	--------------	-----	-------------	-------------	------------------------------------