

Product Discontinuation



EOL_585_16

| | |
|-----------------------|------------|
| ■ Last Order Date: | 2017-02-13 |
| ■ Last Delivery Date: | 2018-02-13 |

Reason: Product portfolio rationalization and lack of demand

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | | Pin to Pin Replacement |
|--------------|---------------|------------|------------|-------------------|---------------|------|---------|------------------------|
| Device | Ordering Code | OPN | Package | Device | Ordering Code | OPN | Package | Y/N |
| 94-4153PBF | SP001522146 | 94-4153PBF | D2Pak | None | None | None | None | N |
| 94-2523 | SP001515640 | 94-2523 | TO-220 | None | None | None | None | N |
| 94-4421 | SP001515602 | 94-4421 | D2Pak | None | None | None | None | N |
| AUXVOF1733 | SP001516988 | AUXVOF1733 | TO-220 | None | None | None | None | N |
| 64-2053 | SP001516430 | 64-2053 | D2Pak | None | None | None | None | N |
| 62-0163PBF | SP001516440 | 62-0163PBF | SO-8 | None | None | None | None | N |
| 64-4047PBF | SP001522452 | 64-4047PBF | D-Pak | None | None | None | None | N |
| 64-4027PBF | SP001517850 | 64-4027PBF | D-Pak | None | None | None | None | N |
| 94-4921 | SP001519998 | 94-4921 | TO-220 | None | None | None | None | N |
| 94-4130 | SP001520008 | 94-4130 | D2Pak | None | None | None | None | N |
| 94-2184 | SP001521460 | 94-2184 | D2Pak | None | None | None | None | N |
| 94-3192 | SP001517110 | 94-3192 | Super220 | None | None | None | None | N |
| 94-5830 | SP001517780 | 94-5830 | Fullpak220 | None | None | None | None | N |
| 94-4164 | SP001521416 | 94-4164 | SOT-223 | None | None | None | None | N |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



EOL_585_16

| | |
|-----------------------|------------|
| ■ Last Order Date: | 2017-02-13 |
| ■ Last Delivery Date: | 2018-02-13 |

| | | | | | | | | |
|---------------|-------------|---------------|----------|--------------|-------------|--------------|------|---|
| 64-3001 | SP001515688 | 64-3001 | SOT-223 | None | None | None | None | N |
| 62-3016PBF | SP001520866 | 62-3016PBF | SOT-223 | None | None | None | None | N |
| 94-2222 | SP001518362 | 94-2222 | D-Pak | None | None | None | None | N |
| 64-4024 | SP001518418 | 64-4024 | D-Pak | None | None | None | None | N |
| 64-4050PBF | SP001520986 | 64-4050PBF | D-Pak | None | None | None | None | N |
| 64-4114PBF | SP001521950 | 64-4114PBF | D-Pak | None | None | None | None | N |
| 94-4888PBF | SP001517044 | 94-4888PBF | D-Pak | None | None | None | None | N |
| 94-2214 | SP001517840 | 94-2214 | D2Pak | None | None | None | None | N |
| 94-2937 | SP001519284 | 94-2937 | TO-220 | None | None | None | None | N |
| 94-2312 | SP001521926 | 94-2312 | D2Pak | None | None | None | None | N |
| 94-3639PBF | SP001517820 | 94-3639PBF | SO-8 | AUIRF7379QTR | SP001520160 | AUIRF7379QTR | SO-8 | Y |
| 94-4806PBF | SP001516314 | 94-4806PBF | SO-8 | AUIRF7103QTR | SP001517980 | AUIRF7103QTR | SO-8 | Y |
| 94-4807PBF | SP001522128 | 94-4807PBF | SO-8 | AUIRF7379QTR | SP001520160 | AUIRF7379QTR | SO-8 | Y |
| IRF7307QTRPBF | SP001522024 | IRF7307QTRPBF | SO-8 | None | None | None | None | N |
| IRF7416QTRPBF | SP001523076 | IRF7416QTRPBF | SO-8 | AUIRF7416QTR | SP001516460 | AUIRF7416QTR | SO-8 | Y |
| 64-2077HM | SP001521384 | 64-2077HM | TO-262 | None | None | None | None | N |
| 64-2103PBF | SP001518426 | 64-2103PBF | D2Pak | None | None | None | None | N |
| AUXCLFR4104 | SP001517026 | AUXCLFR4104 | D-Pak | None | None | None | None | N |
| AUXHE2804STRR | SP001521802 | AUXHE2804STRR | D2Pak | None | None | None | None | N |
| 64-2110PBF | SP001522460 | 64-2110PBF | TO-262 | None | None | None | None | N |
| AUIRFC1324EB | SP001515996 | AUIRFC1324EB | Bare Die | None | None | None | None | N |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



EOL_585_16

■ Last Order Date: 2017-02-13

■ Last Delivery Date: 2018-02-13

| | | | | | | | | |
|--------------|-------------|--------------|----------|------|------|------|------|---|
| AUIRFC1324ED | SP001521534 | AUIRFC1324ED | Bare Die | None | None | None | None | N |
| AUIRFC2804EB | SP001518700 | AUIRFC2804TR | Bare Die | None | None | None | None | N |
| AUIRFC2804TR | SP001519664 | AUIRFC2804TR | Bare Die | None | None | None | None | N |
| AUIRFC3004ED | SP001519134 | AUIRFC3004ED | Bare Die | None | None | None | None | N |
| AUIRFC3805TR | SP001515718 | AUIRFC3805TR | Bare Die | None | None | None | None | N |

If you have any questions, please do not hesitate to contact your local sales office.

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!