

TAIYO YUDEN

Taiyo Yuden (U.S.A.) Inc.
10 N. Martingale Road, Ste.575
Schaumburg, IL60173
Tel (630) 237-2405 Fax (847) 240-1715
<http://www.t-yuden.com>

DISCONTINUATION NOTICE

DATE: September 6, 2013

RE: Discontinuation of Wire-wound Chip Inductors
LBC2518T102K

REF NO.: UTY-DN13-12D

TAIYO YUDEN (U.S.A.), INC hereby gives notice that the following part numbers will be discontinued effective immediately. There is no sales history on those parts and therefore no last orders will be accepted.

Discontinued Part	Replacement Part
LBC2518T102K	LB2518T102K CB2518T102K