



Phoenix Contact Inc.
P.O. BOX 4100
Harrisburg, PA 17111-0100
Phone: 717-944-1300

Product Change Notification

PCN-ICC-7493-2021

| Business Unit | Product Line Code | Type of Change | Action | Date of Issue |
|--------------------------|-------------------|-----------------------------|-------------------------------|---------------|
| ICC - Industrial Cabinet | BE2 | Product Change Notification | Notify Distributors and Field | 12/14/2021 |

The following Phoenix Contact products have been modified. Existing specifications will be met or exceeded. Please review and acknowledge this document and inform your personnel as needed.

Description for Product Change Notification

The insulating material of the FBSR bridges is changing from PA 6.6 V2 to PA 6.6 V0. Switching to this higher quality insulating material enables the FBSR bridges to be used in additional applications with increased fire protection requirements. The technical product features remain unchanged.

Stock Status

Can existing stock still be used? Yes
Is mixture of stock acceptable? No

Transaction Dates

Date modification goes into effect from Germany: 2/1/2022
Expected first shipment (from Phoenix Contact) of the modified products(s): 5/1/2022

Should you have any issues with the timeline or content of this product change, please contact Phoenix Contact using the information below. Customers should acknowledge receipt of the PCN within 30 days of delivery of the PCN; provided, however, that the failure to acknowledge receipt does not affect the product change or the effective date thereof.

Contact Info:

Cory Myer
cmyer@phoenixcontact.com

Thank you,

Alan P. Sappe

Alan Sappe

Product Marketing Manager - Industrial Cabinet Conn.



Phoenix Contact Inc.
P.O. BOX 4100
Harrisburg, PA 17111-0100
Phone: 717-944-1300

Product Change Notification

| Part # | Type Description |
|---------|------------------|
| 3001591 | FBSR 3-5 |
| 3001592 | FBSR 4-5 |
| 3001593 | FBSR 5-5 |
| 3001594 | FBSR 3-6 |
| 3001595 | FBSR 4-6 |
| 3001596 | FBSR 5-6 |
| 3001597 | FBSR 3-8 |
| 3001599 | FBSR 10-8 |
| 3033702 | FBSR 2-5 |
| 3033710 | FBSR 10-5 |
| 3033715 | FBSR 2-6 |
| 3033716 | FBSR 10-6 |
| 3033802 | FBSRH 2-8 |
| 3033803 | FBSRH 3-8 |
| 3033804 | FBSRH 4-8 |
| 3033808 | FBSR 2-8 |
| 3033804 | FBSRH 4-8 |
| 3033808 | FBSR 2-8 |
| 3033809 | FBSR 5-8 |
| 3033812 | FBSRH 2-6 |
| 3033816 | FBSR 16-8 |
| 3033820 | FBSR 1/6/11/16-8 |
| 3033821 | FBSR 1/7/13/16-8 |
| 3033822 | FBSR 1/6/11/14-8 |
| 3000585 | FBSR 4-8 |