

Product Discontinuation Notice

February 2012

Discontinuation of HP Relays



1. Reason: Low market demand

2. Affected parts:

HP relays 	All types	HPO-
---	-----------	------

3. Last time buy: End of August 2012

4. Substitution: None

Any questions, please contact your local Panasonic Electric Works Sales representatives.

(Ref#: T-1246-08)