

PRODUCT ADVISORY NOTICE

KEEPING YOU INFORMED OF PRODUCT CHANGES

To: All Customers, Sales Representatives and Distributors

Date: May 14, 2014

Subject: Select tact switch cover/support plating material change

This Product Advisory Notice is to alert you that Grayhill is changing the material on the cover/support of the 95 Series right angle through-hole tact switches. Samples have been made using the new material and have passed our qualification testing.

Description of Change

Grayhill is changing the plating of the cover/support from a current plating at 100 microinches of Tin to a cover/support plating of 4 microinches of Silver over 100 microinches of Nickel.

Reason for Change

This change is part of a Grayhill Tin whisker mitigation strategy.

Effective Date

Immediately

Part Numbers Affected

95C06A2RAT
95C06A3RAT
95C06A4RAT
95C06B2RAT
95C06B3RAT
95C06B4RAT
95C06C2RAT
95C06C3RAT
95C06C4RAT
95C06D2RAT
95C06D3RAT
95C06D4RAT
95C06E2RAT
95C06E3RAT
95C06E4RAT
95C06F2RAT
95C06F3RAT
95C06F4RAT

Action Required

Please forward this notification and the test report to the appropriate person(s) in your organization. If the change is acceptable, no action is necessary. If you would like to request a copy of the test reports, receive a free sample or have questions, contact your Grayhill, Inc. sales associate.

