

# Product Change Notification

PCN#: RACKS CABLE MGMT- 2018-07-16 Issue Date: 01Aug2018

Impacted Regions: NA EMEA LATAM AP

Reason for Change: Discontinuation Other

**DESCRIPTION OF CHANGE:** (Not required for discontinuation)

The CMR19X84 rack will be discontinued. It's replacement, R2P, is the same aluminum 2-post rack with the only difference being the RU numbering goes from the bottom-up rather than top-down.

**PHOTOS/DRAWING** (where applicable)



**IMPACTED PART NUMBERS AND REPLACEMENT** (where applicable) **PART NUMBERS**

Page 2 contains the impacted part number and the replacement part

**DATES DISCONTINUATION AND NEW PRODUCT AVAILABILITY**

Schedule for Changes	YEAR (YYYY)	Month (MMM)	Day (DD)
New product sample availability date			
Old product discontinuation date	2018	11	1

**\*Important:** After old product discontinuation date, the affected part numbers listed above will continue to be available for sale as long as supplies last. Product may be returned up to 60 days after the product discontinuation date.

**CUSTOMER SERVICE CONTACTS:**

<b>ASIA PACIFIC</b>	AUSTRALIA: 1-800 7263848 <a href="mailto:AUS-CustomerService@panduit.com">AUS-CustomerService@panduit.com</a>	CHINA: 800-820-1900 <a href="mailto:CHN-CustomerService@panduit.com">CHN-CustomerService@panduit.com</a>	HONG KONG: 800-965768 <a href="mailto:CHN-CustomerService@panduit.com">CHN-CustomerService@panduit.com</a>	
	INDIA: 000 800 6501844 (Fixed Line) 000 800 6500369 (Mobile) <a href="mailto:IND-customer_service@panduit.com">IND-customer_service@panduit.com</a>	INDONESIA: 001 803 65 7571 <a href="mailto:SGP-customer_service@panduit.com">SGP-customer_service@panduit.com</a>	JAPAN: +81-3-6863-6000 <a href="mailto:JPN-CS@panduit.com">JPN-CS@panduit.com</a>	
	KOREA: 02-2182-7300 <a href="mailto:KOR-CustomerService@panduit.com">KOR-CustomerService@panduit.com</a>	MALAYSIA: 1800 801435 <a href="mailto:SGP-customer_service@panduit.com">SGP-customer_service@panduit.com</a>	SINGAPORE: 1-800-7263848 <a href="mailto:SGP-CUSTOMER_SERVICE@panduit.com">SGP-CUSTOMER_SERVICE@panduit.com</a>	
	TAIWAN: 0080 165 1487 <a href="mailto:SGP-CUSTOMER_SERVICE@panduit.com">SGP-CUSTOMER_SERVICE@panduit.com</a>	THAILAND: 001-800-65-6385 <a href="mailto:SGP-customer_service@panduit.com">SGP-customer_service@panduit.com</a>		
<b>LATIN AMERICA</b>	BRAZIL: 08000562613 (Toll Free) <a href="mailto:BRA-custservice@panduit.com">BRA-custservice@panduit.com</a>	MEXICO: +52-33-37776000, X80520 01 800 360 86 00 (Toll Free) <a href="mailto:mex-customerservice@panduit.com">mex-customerservice@panduit.com</a>	OTHER LA COUNTRIES: Phone USA 1-708-532-1800 <a href="mailto:TP-CS-INTERNATIONAL@panduit.com">TP-CS-INTERNATIONAL@panduit.com</a>	
	<b>NORTH AMERICA</b>	USA & CANADA: 1-800-777-3300 <a href="mailto:cs@panduit.com">cs@panduit.com</a>	<b>EMEA</b> Phone:: +44 208 6017219 <a href="mailto:EMEA-CustomerServices@panduit.com">EMEA-CustomerServices@panduit.com</a>	

To add a contact or to unsubscribe, please send an e-mail to [PCN@panduit.com](mailto:PCN@panduit.com)

