



PCN - 11 125

Issue Date: December 07 2011

Product Name:	CLINCHER CONNECTORS			
	CLINCHER RECEPTACLE CONNECTORS			
Product Manager:	James Wang			
Subject:	Product Change Notification			
Distribution:	General customer distribution			
Type of Change:	Product Design Change			
Change Description:	To remove the gold plating on the non-functional plating area and plate Au or GXT on the functional area.			
Reason for Change:	To optimize the gold plating area on the terminal. This change will not affect the product performance.			
Affected Parts:	See the PN list in the affected PN file			
Effective Date of Change:	March	07	2012	
Last Time Buy Date:	N/A	N/A	N/A	
Last Disty Return Date:	N/A	N/A	N/A	
Datasheet Attached?	No			
Qual/Test Data Attached?	No			
Samples Availability Date:	December	22	2011	
Available Alternatives?	N/A			
Questions?	<i>Contact your local FCI Representative, or</i>			
	<i>James Wang / Product manager</i>			
	<i>Phone number: 86 513 80167254 / e-mail address:James.wang@fci.com</i>			