



Product Transition Notice		Date 1 Oct 2014
Product	Digi TransPort®, ConnectWAN® and ConnectPort® – Gobi 3000 Module Migration Notice	
Notice Number	141001-0833	

Reason for Notification:

<input type="checkbox"/> New Product Introduction	<input checked="" type="checkbox"/> Product Transition
<input type="checkbox"/> Customer Requirement	<input checked="" type="checkbox"/> Product Discontinuation
<input type="checkbox"/> Quality Improvement	<input type="checkbox"/> Product Enhancement
<input type="checkbox"/> Change of Production Location	<input type="checkbox"/> Other (Brand Change)

Audience	All Digi TransPort, ConnectWAN, and ConnectPort distributors and customers
-----------------	--

Product Notice	<p>Huawei has discontinued module support for their Gobi 3000 embedded WWAN module. As a result, Digi is replacing the Gobi 3000-based module (-U8 part numbers, supporting EVDO and HSPA) with new 3G and 4G LTE options. Timing and replacement part numbers are defined below.</p> <p>Last Time Buy: November 28, 2014 (pending availability of modules) Last Time Ship: December 31, 2014</p> <p>The supply of Gobi 3000 modules is limited. Customers are encouraged to identify their replacement part number and begin migration as soon as possible.</p> <p>Use the table below and consult with your Digi or Digi partner sales representative to identify the appropriate transition module.</p> <p>Replacement products are certified and orderable now.</p> <ul style="list-style-type: none"> - The -U9 variant supports global HSPA+ networks (e.g. AT&T, Vodafone, Rogers, Telus, Orange) - The -L1 variant supports 4G LTE networks outside of North America and global HSPA+ networks - The -L5 variant uses Qualcomm Gobi® 4G LTE technology to support Verizon, AT&T, and Sprint 2G/3G/4G LTE networks and global HSPA+ networks. - The -B1 and -B2 support Sprint and Verizon 1xRTT networks.
-----------------------	--

	New 4G LTE options (-L6, -L7, and -L8) will be available in late-October and will be described in a separate notice.
--	--

Affected Products	All –U8 variants of the TransPort WR21, WR41, and WR44 (including R and RR variants), Connect WAN 3G, ConnectPort X4 and X4H, and Utility Communication Hub. A full table is provided below.
--------------------------	---


Timing	Last Time Buy: November 28, 2014 (pending availability of modules) Last Time Ship: December 31, 2014
---------------	---

Action Required	Replacement part numbers are listed in the table below. Customers are encouraged to identify their preferred replacement part number and modify future orders to transition to the replacement part number. Distribution Partners, please note: <ul style="list-style-type: none"> 1) Last-Time-Buy orders are non-cancellable and non-returnable (NCNR) 2) Please reference the end-customer on your Purchase Order to assist in prioritizing fulfilment
------------------------	--

Authorization	<i>Andrew Lund</i> <i>Product Marketing Manager</i> <i>(612) 247-1127</i> andrew.lund@digicom.com
----------------------	---

Change Description	Detailed information on the replacement variants is provided below.
---------------------------	---

The graphic below illustrates the section of a TransPort model number that identifies the embedded cellular module.



Part numbers with -U8 in Field 2 will migrate to one of the module options described in the chart below.

Cellular Module Options

SKU Reference	Network Compatibility	Vendor	Model	LTE Frequency (B = Band)	HSPA Support	CDMA Support	Product Availability
-L1	International EMEA/APAC	Huawei	ME909u-521	800 (B20) 850 (B5) 900 (B8) 1800 (B3) 1900 (B2) 2100 (B1) 2600 (B7)	<u>HSPA+</u> 850/900/1900/ 2100 <u>EDGE/GPRS</u> 850/900/1800/ 1900	None	WR21 WR41 WR44
-L5	Verizon, AT&T, and Sprint LTE with EVDO/1xRTT and HSPA+/EDGE Fallback	Sierra Wireless	MC7354	700(B13, Verizon) 700(B17, AT&T) AWS (B4) 850(B5) 1900(B2) 1900(B25, Sprint)	<u>HSPA+</u> 850/900/AWS/ 1900/2100 <u>EDGE</u> 850/900/1800/ 1900	<u>EVDO /1XRTT</u> 800/1900	WR21 WR41 WR44
-U9	Global HSPA+	Telit	HE910	None	<u>HSPA+</u> 850/900/AWS1700/ 1900/2100 <u>EDGE</u> 850/900/1800/1900	None	WR11 WR21 WR41 WR44 Connect WAN ConnectPort X4/H
-B1	Sprint 1xRTT	uBlox	FW2763P	None	None	<u>1XRTT</u> 800/1900	WR21 Connect WAN ConnectPort X4/H
-B2	Verizon 1xRTT	uBlox	FW2763P	None	None	<u>1XRTT</u> 800/1900	WR21 Connect WAN ConnectPort X4/H

FAQ: "Today..."	Currently using	My new part #
I'm using HSPA+ and want to stay with HSPA+ (AT&T, Vodafone, Orange, Rogers, Telus, et al)	-U8	-U9
I'm using Verizon 2G and only need Verizon 2G	-U8	-B2
I'm using Verizon 3G and want to stay Verizon 3G	-U8	-L5
I'm using Sprint 2G and only need Sprint 2G	-U8	-B1
I'm using Sprint 3G and want to stay Sprint 3G	-U8	-L5
I need carrier flexibility across Verizon, Sprint, & AT&T	-U8	-L5

Affected Products	All –U8 variants of the TransPort, ConnectWAN, and ConnectPort products. Full list provided below.
--------------------------	---

Table 1: Affected TransPort WR21's and Replacement Product

EOL Part Number	HSPA+ Replacement	Gobi 4G LTE Replacement	Sprint 1xRTT Replacement	Verizon 1xRTT Replacement
WR21-U82B-DE1-SU	WR21-U92B-DE1-SU	WR21-L52B-DE1-SU	WR21-B12B-DE1-SU	WR21-B22B-DE1-SU
WR21-U82B-DE1-SH	WR21-U92B-DE1-SH	WR21-L52B-DE1-SH	WR21-B12B-DE1-SH	WR21-B22B-DE1-SH
WR21-U82B-DE1-SF	WR21-U92B-DE1-SF	WR21-L52B-DE1-SF	WR21-B12B-DE1-SF	WR21-B22B-DE1-SF
WR21-U82B-DE1-SD	WR21-U92B-DE1-SD	WR21-L52B-DE1-SD	WR21-B12B-DE1-SD	WR21-B22B-DE1-SD
WR21-U82B-DE1-CW	None	None	None	None
WR21-U82B-DB1-SU	WR21-U92B-DB1-SU	WR21-L52B-DB1-SU	WR21-B12B-DB1-SU	WR21-B22B-DB1-SU
WR21-U82B-DB1-SH	WR21-U92B-DB1-SH	WR21-L52B-DB1-SH	WR21-B12B-DB1-SH	WR21-B22B-DB1-SH
WR21-U82B-DB1-SF	WR21-U92B-DB1-SF	WR21-L52B-DB1-SF	WR21-B12B-DB1-SF	WR21-B22B-DB1-SF
WR21-U82B-D50-SD	WR21-U92B-D50-SD	WR21-L52B-D50-SD	WR21-B12B-D50-SD	WR21-B22B-D50-SD
WR21-U82B-D44-SW	WR21-U92B-D44-SW	WR21-L52B-D44-SW	WR21-B12B-D44-SW	WR21-B22B-D44-SW
WR21-U82B-D40-SF	WR21-U92B-D40-SF	WR21-L52B-D40-SF	WR21-B12B-D40-SF	WR21-B22B-D40-SF
WR21-U82B-D34-SF	WR21-U92B-D34-SF	WR21-L52B-D34-SF	WR21-B12B-D34-SF	WR21-B22B-D34-SF
WR21-U82B-D25-SW	WR21-U92B-D25-SW	WR21-L52B-D25-SW	WR21-B12B-D25-SW	WR21-B22B-D25-SW
WR21-U82B-D25-SA	WR21-U92B-D25-SA	WR21-L52B-D25-SA	WR21-B12B-D25-SA	WR21-B22B-D25-SA

WR21-U82B-D14-SW	WR21-U92B-D14-SW	WR21-L52B-D14-SW	WR21-B12B-D14-SW	WR21-B22B-D14-SW
WR21-U82B-D14-SA	WR21-U92B-D14-SA	WR21-L52B-D14-SA	WR21-B12B-D14-SA	WR21-B22B-D14-SA
WR21-U82A-DE1-TH	WR21-U92A-DE1-TH	WR21-L52A-DE1-TH	WR21-B12A-DE1-TH	WR21-B22A-DE1-TH
WR21-U82A-DE1-TB	WR21-U92A-DE1-TB	WR21-L52A-DE1-TB	WR21-B12A-DE1-TB	WR21-B22A-DE1-TB
WR21-U82A-DE1-TA	WR21-U92A-DE1-TA	WR21-L52A-DE1-TA	WR21-B12A-DE1-TA	WR21-B22A-DE1-TA
WR21-U82A-DB1-TH	WR21-U92A-DB1-TH	WR21-L52A-DB1-TH	WR21-B12A-DB1-TH	WR21-B22A-DB1-TH
WR21-U82A-DB1-TA	WR21-U92A-DB1-TA	WR21-L52A-DB1-TA	WR21-B12A-DB1-TA	WR21-B22A-DB1-TA
WR21-U82A-D42-TB	WR21-U92A-D42-TB	WR21-L52A-D42-TB	WR21-B12A-D42-TB	WR21-B22A-D42-TB
WR21-U82A-D39-ZZ	WR21-U92A-D39-ZZ	WR21-L52A-D39-ZZ	WR21-B12A-D39-ZZ	WR21-B22A-D39-ZZ
WR21-U81B-DE1-SU	WR21-U91B-DE1-SU	WR21-L51B-DE1-SU	WR21-B11B-DE1-SU	WR21-B21B-DE1-SU
WR21-U81B-DE1-SN	WR21-U91B-DE1-SN	WR21-L51B-DE1-SN	WR21-B11B-DE1-SN	WR21-B21B-DE1-SN
WR21-U81B-DE1-SH	WR21-U91B-DE1-SH	WR21-L51B-DE1-SH	WR21-B11B-DE1-SH	WR21-B21B-DE1-SH
WR21-U81B-DE1-SF	WR21-U91B-DE1-SF	WR21-L51B-DE1-SF	WR21-B11B-DE1-SF	WR21-B21B-DE1-SF
WR21-U81B-DE1-SD	WR21-U91B-DE1-SD	WR21-L51B-DE1-SD	WR21-B11B-DE1-SD	WR21-B21B-DE1-SD
WR21-U81B-DE1-SB	WR21-U91B-DE1-SB	WR21-L51B-DE1-SB	WR21-B11B-DE1-SB	WR21-B21B-DE1-SB
WR21-U81B-DE1-SA	WR21-U91B-DE1-SA	WR21-L51B-DE1-SA	WR21-B11B-DE1-SA	WR21-B21B-DE1-SA
WR21-U81B-DB1-SU	WR21-U91B-DB1-SU	WR21-L51B-DB1-SU	WR21-B11B-DB1-SU	WR21-B21B-DB1-SU
WR21-U81B-DB1-SN	WR21-U91B-DB1-SN	WR21-L51B-DB1-SN	WR21-B11B-DB1-SN	WR21-B21B-DB1-SN
WR21-U81B-DB1-SH	WR21-U91B-DB1-SH	WR21-L51B-DB1-SH	WR21-B11B-DB1-SH	WR21-B21B-DB1-SH
WR21-U81B-DB1-SF	WR21-U91B-DB1-SF	WR21-L51B-DB1-SF	WR21-B11B-DB1-SF	WR21-B21B-DB1-SF
WR21-U81B-D37-SF	WR21-U91B-D37-SF	WR21-L51B-D37-SF	WR21-B11B-D37-SF	WR21-B21B-D37-SF
WR21-U81B-D31-SU	WR21-U91B-D31-SU	WR21-L51B-D31-SU	WR21-B11B-D31-SU	WR21-B21B-D31-SU
WR21-U81B-D25-SW	WR21-U91B-D25-SW	WR21-L51B-D25-SW	WR21-B11B-D25-SW	WR21-B21B-D25-SW
WR21-U81B-D24-SW	WR21-U91B-D24-SW	WR21-L51B-D24-SW	WR21-B11B-D24-SW	WR21-B21B-D24-SW
WR21-U81B-D17-SD	WR21-U91B-D17-SD	WR21-L51B-D17-SD	WR21-B11B-D17-SD	WR21-B21B-D17-SD
WR21-U81A-DE1-TH	WR21-U91A-DE1-TH	WR21-L51A-DE1-TH	WR21-B11A-DE1-TH	WR21-B21A-DE1-TH
EOL Part Number	HSPA+ Replacement	Gobi 4G LTE Replacement	Sprint 1xRTT Replacement	Verizon 1xRTT Replacement
WR21-U81A-DE1-TB	WR21-U91A-DE1-TB	WR21-L51A-DE1-TB	WR21-B11A-DE1-TB	WR21-B21A-DE1-TB
WR21-U81A-DE1-TA	WR21-U91A-DE1-TA	WR21-L51A-DE1-TA	WR21-B11A-DE1-TA	WR21-B21A-DE1-TA
WR21-U81A-DB1-TH	WR21-U91A-DB1-TH	WR21-L51A-DB1-TH	WR21-B11A-DB1-TH	WR21-B21A-DB1-TH
WR21-U81A-DB1-TB	WR21-U91A-DB1-TB	WR21-L51A-DB1-TB	WR21-B11A-DB1-TB	WR21-B21A-DB1-TB
WR21-U81A-DB1-TA	WR21-U91A-DB1-TA	WR21-L51A-DB1-TA	WR21-B11A-DB1-TA	WR21-B21A-DB1-TA
WR21-U81A-D48-TA	WR21-U91A-D48-TA	WR21-L51A-D48-TA	WR21-B11A-D48-TA	WR21-B21A-D48-TA
WR21-U81A-D42-TB	WR21-U91A-D42-TB	WR21-L51A-D42-TB	WR21-B11A-D42-TB	WR21-B21A-D42-TB
WR21-U81A-D41-TB	WR21-U91A-D41-TB	WR21-L51A-D41-TB	WR21-B11A-D41-TB	WR21-B21A-D41-TB

Table 2: Affected TransPort WR41's and Replacement Product

EOL Part Number	HSPA+ Replacement	Gobi 4G LTE Replacement	Sprint 1xRTT Replacement	Verizon 1xRTT Replacement
WR41-U8T2-NE1-SU	WR41-U9T2-NE1-SU	WR41-L5T2-NE1-SU	None	None
WR41-U8T2-DV1-XD	WR41-U9T2-DE1-XD	WR41-L5T2-DE1-XD	None	None
WR41-U8T2-DV1-SU	WR41-U9T2-DE1-SU	WR41-L5T2-DE1-SU	None	None
WR41-U8T2-DA1-XH	WR41-U9T2-DB1-XH	WR41-L5T2-DB1-XH	None	None
WR41-U8T2-DA1-SU	WR41-U9T2-DB1-SU	WR41-L5T2-DB1-SU	None	None
WR41-U8T1-NE1-SU	WR41-U9T1-NE1-SU	WR41-L5T1-NE1-SU	None	None
WR41-U8T1-DV1-XD	WR41-U9T1-DE1-XD	WR41-L5T1-DE1-XD	None	None
WR41-U8T1-DA1-XD	WR41-U9T1-DB1-XD	WR41-L5T1-DB1-XD	None	None
WR41-U8T1-DA1-SU	WR41-U9T1-DB1-SU	WR41-L5T1-DB1-SU	None	None
WR41-U8S1-NV1-SU	WR41-U9S1-NE1-SU	WR41-L5S1-NE1-SU	None	None
WR41-U8S1-DV1-XH	WR41-U9S1-DE1-XH	WR41-L5S1-DE1-XH	None	None
WR41-U8S1-DV1-XD	WR41-U9S1-DE1-XD	WR41-L5S1-DE1-XD	None	None
WR41-U8S1-DV1-SU	WR41-U9S1-DE1-SU	WR41-L5S1-DE1-SU	None	None
WR41-U8S1-DA1-SU	WR41-U9S1-DB1-SU	WR41-L5S1-DB1-SU	None	None

WR41-U8P3-DV1-XH	WR41-U9P3-DE1-XH	WR41-L5P3-DE1-XH	None	None
WR41-U8G1-WV1-XH	WR41-U9G1-NE1-XH	WR41-L5G1-NE1-XH	None	None
WR41-U8G1-WV1-SU	WR41-U9G1-NE1-SU	WR41-L5G1-NE1-SU	None	None
WR41-U8G1-WE1-SU	WR41-U9G1-NE1-SU	WR41-L5G1-NE1-SU	None	None
WR41-U8G1-NV1-XH	WR41-U9G1-NE1-XH	WR41-L5G1-NE1-XH	None	None
WR41-U8G1-NV1-XF	WR41-U9G1-NE1-XF	WR41-L5G1-NE1-XF	None	None
WR41-U8G1-NV1-XD	WR41-U9G1-NE1-XD	WR41-L5G1-NE1-XD	None	None
WR41-U8G1-NV1-SU	WR41-U9G1-NE1-SU	WR41-L5G1-NE1-SU	None	None
WR41-U8G1-NE1-SU	WR41-U9G1-NE1-SU	WR41-L5G1-NE1-SU	None	None
WR41-U8G1-NA1-XD	WR41-U9G1-NB1-XD	WR41-L5G1-NB1-XD	None	None
WR41-U8G1-DV1-XH	WR41-U9G1-DE1-XH	WR41-L5G1-DE1-XH	None	None
WR41-U8G1-DV1-XD	WR41-U9G1-DE1-XD	WR41-L5G1-DE1-XD	None	None
WR41-U8G1-DV1-SU	WR41-U9G1-DE1-SU	WR41-L5G1-DE1-SU	None	None
WR41-U8G1-DV1-SF	WR41-U9G1-DE1-SF	WR41-L5G1-DE1-SF	None	None
WR41-U8G1-DV1-SB	WR41-U9G1-DE1-SB	WR41-L5G1-DE1-SB	None	None
WR41-U8G1-DE1-XD	WR41-U9G1-DE1-XD	WR41-L5G1-DE1-XD	None	None
WR41-U8G1-DA1-XB	WR41-U9G1-DB1-XB	WR41-L5G1-DB1-XB	None	None
WR41-U8G1-DA1-SU	WR41-U9G1-DB1-SU	WR41-L5G1-DB1-SU	None	None
WR41-U8G1-DA1-SD	WR41-U9G1-DB1-SD	WR41-L5G1-DB1-SD	None	None
WR41-U8G1-DA1-SB	WR41-U9G1-DB1-SB	WR41-L5G1-DB1-SB	None	None
WR41-U8F1-WV1-SU	WR41-U9F1-NE1-SU	WR41-L5F1-NE1-SU	None	None
WR41-U8F1-NV1-SF	WR41-U9F1-NE1-SF	WR41-L5F1-NE1-SF	None	None
WR41-U8F1-DV1-SF	WR41-U9F1-DE1-SF	WR41-L5F1-DE1-SF	None	None
WR41-U8F1-DA1-XD	WR41-U9F1-DB1-XD	WR41-L5F1-DB1-XD	None	None
WR41-U8A4-W13-SB	WR41-U9A4-N13-SB	WR41-L5A4-N13-SB	None	None
WR41-U8A3-WV1-XH	WR41-U9A3-NE1-XH	WR41-L5A3-NE1-XH	None	None
EOL Part Number	HSPA+ Replacement	Gobi 4G LTE Replacement	Sprint 1xRTT Replacement	Verizon 1xRTT Replacement
WR41-U8A3-WV1-SF	WR41-U9A3-NE1-SF	WR41-L5A3-NE1-SF	None	None
WR41-U8A3-WE1-SU	WR41-U9A3-NE1-SU	WR41-L5A3-NE1-SU	None	None
WR41-U8A3-W13-SB	WR41-U9A3-N13-SB	WR41-L5A3-N13-SB	None	None
WR41-U8A3-NV1-XD	WR41-U9A3-NE1-XD	WR41-L5A3-NE1-XD	None	None
WR41-U8A3-DV1-XH	WR41-U9A3-DE1-XH	WR41-L5A3-DE1-XH	None	None
WR41-U8A3-DV1-XD	WR41-U9A3-DE1-XD	WR41-L5A3-DE1-XD	None	None
WR41-U8A3-DV1-SU	WR41-U9A3-DE1-SU	WR41-L5A3-DE1-SU	None	None
WR41-U8A3-DA1-SU	WR41-U9A3-DB1-SU	WR41-L5A3-DB1-SU	None	None
WR41-U8A3-DA1-SF	WR41-U9A3-DB1-SF	WR41-L5A3-DB1-SF	None	None
WR41-U8A3-D31-SU	WR41-U9A3-D31-SU	WR41-L5A3-D31-SU	None	None
WR41-U8A1-DV1-SU	WR41-U9A1-DE1-SU	WR41-L5A1-DE1-SU	None	None
WR41-U800-WV1-XH	WR41-U900-NE1-XH	WR41-L500-NE1-XH	None	None
WR41-U800-WV1-XD	WR41-U900-NE1-XD	WR41-L500-NE1-XD	None	None
WR41-U800-WV1-SU	WR41-U900-NE1-SU	WR41-L500-NE1-SU	None	None
WR41-U800-WV1-SF	WR41-U900-NE1-SF	WR41-L500-NE1-SF	None	None
WR41-U800-WA1-XH	WR41-U900-NB1-XH	WR41-L500-NB1-XH	None	None

WR41-U800-WA1-XD	WR41-U900-NB1-XD	WR41-L500-NB1-XD	None	None
WR41-U800-WA1-SU	WR41-U900-NB1-SU	WR41-L500-NB1-SU	None	None
WR41-U800-WA1-SF	WR41-U900-NB1-SF	WR41-L500-NB1-SF	None	None
WR41-U800-W24-SW	WR41-U900-N24-SW	WR41-L500-N24-SW	None	None
WR41-U800-NV1-XD	WR41-U900-NE1-XD	WR41-L500-NE1-XD	None	None
WR41-U800-NV1-SU	WR41-U900-NE1-SU	WR41-L500-NE1-SU	None	None
WR41-U800-NV1-SF	WR41-U900-NE1-SF	WR41-L500-NE1-SF	None	None
WR41-U800-NE1-SF	WR41-U900-NE1-SF	WR41-L500-NE1-SF	None	None
WR41-U800-NA1-XD	WR41-U900-NB1-XD	WR41-L500-NB1-XD	None	None
WR41-U800-NA1-SU	WR41-U900-NB1-SU	WR41-L500-NB1-SU	None	None
WR41-U800-NA1-SF	WR41-U900-NB1-SF	WR41-L500-NB1-SF	None	None
WR41-U800-DV1-XH	WR41-U900-DE1-XH	WR41-L500-DE1-XH	None	None
WR41-U800-DV1-SU	WR41-U900-DE1-SU	WR41-L500-DE1-SU	None	None
WR41-U800-DV1-SF	WR41-U900-DE1-SF	WR41-L500-DE1-SF	None	None
WR41-U800-DV1-SB	WR41-U900-DE1-SB	WR41-L500-DE1-SB	None	None
WR41-U800-DE3-SU	WR41-U900-DE3-SU	WR41-L500-DE3-SU	None	None
WR41-U800-DE1-XD	WR41-U900-DE1-XD	WR41-L500-DE1-XD	None	None
WR41-U800-DE1-SU	WR41-U900-DE1-SU	WR41-L500-DE1-SU	None	None
WR41-U800-DA1-XD	WR41-U900-DB1-XD	WR41-L500-DB1-XD	None	None
WR41-U800-DA1-SU	WR41-U900-DB1-SU	WR41-L500-DB1-SU	None	None
WR41-U800-DA1-SF	WR41-U900-DB1-SF	WR41-L500-DB1-SF	None	None
WR41-U800-DA1-SB	WR41-U900-DB1-SB	WR41-L500-DB1-SB	None	None
WR41-U800-D24-SW	WR41-U900-D24-SW	WR41-L500-D24-SW	None	None
WR41-U800-D12-SF	WR41-U900-D12-SF	WR41-L500-D12-SF	None	None

Table 3: Affected TransPort WR44's and Replacement Product

EOL Part Number	HSPA+ Replacement	Gobi 4G LTE Replacement	Sprint 1xRTT Replacement	Verizon 1xRTT Replacement
WR44-U8T2-NE1-SU	WR44-U9T2-NE1-SU	WR44-L5T2-NE1-SU	None	None
WR44-U8T2-NE1-SF	WR44-U9T2-NE1-SF	WR44-L5T2-NE1-SF	None	None
WR44-U8T2-CE1-RD	WR44-U9T2-CE1-RD	WR44-L5T2-CE1-RD	None	None
WR44-U8T1-NE1-SU	WR44-U9T1-NE1-SU	WR44-L5T1-NE1-SU	None	None
WR44-U8S1-NE1-SU	WR44-U9S1-NE1-SU	WR44-L5S1-NE1-SU	None	None
WR44-U8S1-NE1-RD	WR44-U9S1-NE1-RD	WR44-L5S1-NE1-RD	None	None
WR44-U8S1-LE2-XD	WR44-U9S1-LE2-XD	WR44-L5S1-LE2-XD	None	None
WR44-U8S1-CE1-SU	WR44-U9S1-CE1-SU	WR44-L5S1-CE1-SU	None	None
WR44-U8S1-CE1-RH	WR44-U9S1-CE1-RH	WR44-L5S1-CE1-RH	None	None
WR44-U8S1-CE1-RD	WR44-U9S1-CE1-RD	WR44-L5S1-CE1-RD	None	None
WR44-U8P1-FE2-XD	WR44-U9P1-FE2-XD	WR44-L5P1-FE2-XD	None	None
WR44-U8P1-C36-SW	WR44-U9P1-C36-SW	WR44-L5P1-C36-SW	None	None
WR44-U8G8-NE1-MD	WR44-U9G8-NE1-MD	WR44-L5G8-NE1-MD	None	None

WR44-U8G8-NE1-MB	WR44-U9G8-NE1-MB	WR44-L5G8-NE1-MB	None	None
WR44-U8G8-N27-MD	WR44-U9G8-N27-MD	WR44-L5G8-N27-MD	None	None
WR44-U8G8-CE1-MD	WR44-U9G8-CE1-MD	WR44-L5G8-CE1-MD	None	None
WR44-U8G4-NE5-MB	WR44-U9G4-NE5-MB	WR44-L5G4-NE5-MB	None	None
WR44-U8G4-NE2-MD	WR44-U9G4-NE2-MD	WR44-L5G4-NE2-MD	None	None
WR44-U8G4-NE1-MD	WR44-U9G4-NE1-MD	WR44-L5G4-NE1-MD	None	None
WR44-U8G4-NE1-MB	WR44-U9G4-NE1-MB	WR44-L5G4-NE1-MB	None	None
WR44-U8G4-CE1-MD	WR44-U9G4-CE1-MD	WR44-L5G4-CE1-MD	None	None
WR44-U8G4-CE1-MB	WR44-U9G4-CE1-MB	WR44-L5G4-CE1-MB	None	None
WR44-U8G4-CC1-MB	WR44-U9G4-CC1-MB	WR44-L5G4-CC1-MB	None	None
WR44-U8G1-NE1-XH	WR44-U9G1-NE1-XH	WR44-L5G1-NE1-XH	None	None
WR44-U8G1-NE1-XD	WR44-U9G1-NE1-XD	WR44-L5G1-NE1-XD	None	None
WR44-U8G1-NE1-SU	WR44-U9G1-NE1-SU	WR44-L5G1-NE1-SU	None	None
WR44-U8G1-NE1-RH	WR44-U9G1-NE1-RH	WR44-L5G1-NE1-RH	None	None
WR44-U8G1-NE1-RD	WR44-U9G1-NE1-RD	WR44-L5G1-NE1-RD	None	None
WR44-U8G1-N24-RD	WR44-U9G1-N24-RD	WR44-L5G1-N24-RD	None	None
WR44-U8G1-ME2-XH	WR44-U9G1-ME2-XH	WR44-L5G1-ME2-XH	None	None
WR44-U8G1-CE5-XH	WR44-U9G1-CE5-XH	WR44-L5G1-CE5-XH	None	None
WR44-U8G1-CE1-XH	WR44-U9G1-CE1-XH	WR44-L5G1-CE1-XH	None	None
WR44-U8G1-CE1-XD	WR44-U9G1-CE1-XD	WR44-L5G1-CE1-XD	None	None
WR44-U8G1-CE1-SU	WR44-U9G1-CE1-SU	WR44-L5G1-CE1-SU	None	None
WR44-U8G1-CE1-RH	WR44-U9G1-CE1-RH	WR44-L5G1-CE1-RH	None	None
WR44-U8G1-CE1-RD	WR44-U9G1-CE1-RD	WR44-L5G1-CE1-RD	None	None
WR44-U8F1-NE1-RH	WR44-U9F1-NE1-RH	WR44-L5F1-NE1-RH	None	None
WR44-U8F1-NE1-RF	WR44-U9F1-NE1-RF	WR44-L5F1-NE1-RF	None	None
EOL Part Number	HSPA+ Replacement	Gobi 4G LTE Replacement	Sprint 1xRTT Replacement	Verizon 1xRTT Replacement
WR44-U8F1-NE1-RD	WR44-U9F1-NE1-RD	WR44-L5F1-NE1-RD	None	None
WR44-U8F1-CE1-RD	WR44-U9F1-CE1-RD	WR44-L5F1-CE1-RD	None	None
WR44-U8F1-C38-RD	WR44-U9F1-C38-RD	WR44-L5F1-C38-RD	None	None
WR44-U8A3-NE1-XH	WR44-U9A3-NE1-XH	WR44-L5A3-NE1-XH	None	None
WR44-U8A3-NE1-XD	WR44-U9A3-NE1-XD	WR44-L5A3-NE1-XD	None	None
WR44-U8A3-NE1-SU	WR44-U9A3-NE1-SU	WR44-L5A3-NE1-SU	None	None
WR44-U8A3-NE1-SF	WR44-U9A3-NE1-SF	WR44-L5A3-NE1-SF	None	None
WR44-U8A3-NE1-RD	WR44-U9A3-NE1-RD	WR44-L5A3-NE1-RD	None	None
WR44-U8A3-N13-SB	WR44-U9A3-N13-SB	WR44-L5A3-N13-SB	None	None
WR44-U8A3-CE1-XH	WR44-U9A3-CE1-XH	WR44-L5A3-CE1-XH	None	None
WR44-U8A3-CE1-XD	WR44-U9A3-CE1-XD	WR44-L5A3-CE1-XD	None	None
WR44-U8A3-CE1-SU	WR44-U9A3-CE1-SU	WR44-L5A3-CE1-SU	None	None
WR44-U8A3-CE1-RH	WR44-U9A3-CE1-RH	WR44-L5A3-CE1-RH	None	None
WR44-U8A3-CE1-RD	WR44-U9A3-CE1-RD	WR44-L5A3-CE1-RD	None	None
WR44-U8A3-C13-SB	WR44-U9A3-C13-SB	WR44-L5A3-C13-SB	None	None
WR44-U808-NE1-MD	WR44-U908-NE1-MD	WR44-L508-NE1-MD	None	None
WR44-U808-CE1-MD	WR44-U908-CE1-MD	WR44-L508-CE1-MD	None	None

WR44-U804-NE1-MD	WR44-U904-NE1-MD	WR44-L504-NE1-MD	None	None
WR44-U804-CE1-MD	WR44-U904-CE1-MD	WR44-L504-CE1-MD	None	None
WR44-U800-NE2-SF	WR44-U900-NE2-SF	WR44-L500-NE2-SF	None	None
WR44-U800-NE1-XH	WR44-U900-NE1-XH	WR44-L500-NE1-XH	None	None
WR44-U800-NE1-XD	WR44-U900-NE1-XD	WR44-L500-NE1-XD	None	None
WR44-U800-NE1-SU	WR44-U900-NE1-SU	WR44-L500-NE1-SU	None	None
WR44-U800-NE1-RH	WR44-U900-NE1-RH	WR44-L500-NE1-RH	None	None
WR44-U800-NE1-RF	WR44-U900-NE1-RF	WR44-L500-NE1-RF	None	None
WR44-U800-NE1-RD	WR44-U900-NE1-RD	WR44-L500-NE1-RD	None	None
WR44-U800-N24-RD	WR44-U900-N24-RD	WR44-L500-N24-RD	None	None
WR44-U800-M12-SF	WR44-U900-M12-SF	WR44-L500-M12-SF	None	None
WR44-U800-LE2-XD	WR44-U900-LE2-XD	WR44-L500-LE2-XD	None	None
WR44-U800-LE2-SF	WR44-U900-LE2-SF	WR44-L500-LE2-SF	None	None
WR44-U800-L25-SW	WR44-U900-L25-SW	WR44-L500-L25-SW	None	None
WR44-U800-L12-SF	WR44-U900-L12-SF	WR44-L500-L12-SF	None	None
WR44-U800-GE2-XD	WR44-U900-GE2-XD	WR44-L500-GE2-XD	None	None
WR44-U800-G12-SF	WR44-U900-G12-SF	WR44-L500-G12-SF	None	None
WR44-U800-FE2-XH	WR44-U900-FE2-XH	WR44-L500-FE2-XH	None	None
WR44-U800-FE2-XD	WR44-U900-FE2-XD	WR44-L500-FE2-XD	None	None
WR44-U800-FE2-SF	WR44-U900-FE2-SF	WR44-L500-FE2-SF	None	None
WR44-U800-FC2-XH	WR44-U900-FC2-XH	WR44-L500-FC2-XH	None	None
WR44-U800-F25-SW	WR44-U900-F25-SW	WR44-L500-F25-SW	None	None
WR44-U800-F12-SF	WR44-U900-F12-SF	WR44-L500-F12-SF	None	None
WR44-U800-CE3-SU	WR44-U900-CE3-SU	WR44-L500-CE3-SU	None	None
WR44-U800-CE2-SU	WR44-U900-CE2-SU	WR44-L500-CE2-SU	None	None
EOL Part Number	HSPA+ Replacement	Gobi 4G LTE Replacement	Sprint 1xRTT Replacement	Verizon 1xRTT Replacement
WR44-U800-CE2-RD	WR44-U900-CE2-RD	WR44-L500-CE2-RD	None	None
WR44-U800-CE1-XH	WR44-U900-CE1-XH	WR44-L500-CE1-XH	None	None
WR44-U800-CE1-XD	WR44-U900-CE1-XD	WR44-L500-CE1-XD	None	None
WR44-U800-CE1-SU	WR44-U900-CE1-SU	WR44-L500-CE1-SU	None	None
WR44-U800-CE1-SN	WR44-U900-CE1-SN	WR44-L500-CE1-SN	None	None
WR44-U800-CE1-SF	WR44-U900-CE1-SF	WR44-L500-CE1-SF	None	None
WR44-U800-CE1-RH	WR44-U900-CE1-RH	WR44-L500-CE1-RH	None	None
WR44-U800-CE1-RD	WR44-U900-CE1-RD	WR44-L500-CE1-RD	None	None
WR44-U800-C24-SW	WR44-U900-C24-SW	WR44-L500-C24-SW	None	None
WR44-U800-C24-RD	WR44-U900-C24-RD	WR44-L500-C24-RD	None	None
WR44-U800-C16-SF	WR44-U900-C16-SF	WR44-L500-C16-SF	None	None
WR44-U800-C12-SF	WR44-U900-C12-SF	WR44-L500-C12-SF	None	None
WR44-U5A3-D15-XD	WR44-U5A3-D15-XD	WR44-U5A3-D15-XD	None	None

Table 4: Affected ConnectPort X4's and Replacement Product

EOL Part Number	HSPA+ Replacement	Gobi 4G LTE Replacement	Sprint 1xRTT Replacement	Verizon 1xRTT Replacement
X4-Z2U-U805	X4-Z2U-U905	None	X4-Z2U-B105	X4-Z2U-B205
X4-Z2U-U801-A	X4-Z2U-U901-A	None	X4-Z2U-B101-A	X4-Z2U-B201-A
X4-Z2J-U805	X4-Z2J-U905	None	X4-Z2J-B105	X4-Z2J-B205
X4-Z2J-U801-W	X4-Z2J-U901-W	None	None	None
X4-Z1U-U805	X4-Z1U-U905	None	X4-Z1U-B105	X4-Z1U-B205
X4-Z1U-U801-A	X4-Z1U-U901-A	None	X4-Z1U-B101-A	X4-Z1U-B201-A
X4-Z1J-U805	X4-Z1J-U905	None	X4-Z1J-B105	X4-Z1J-B205
X4-Z1J-U801-W	X4-Z1J-U901-W	None	None	None
X4-Z1J-U801-CW	None	None	None	None
X4-P8J-U805	X4-P8J-U905	None	X4-P8J-B105	X4-P8J-B205
X4-P8J-U801-W	X4-P8J-U901-W	None	None	None
X4-M91-U805	X4-M91-U905	None	X4-M91-B105	X4-M91-B205
X4-M91-U801-A	X4-M91-U901-A	None	X4-M91-B101-A	X4-M91-B201-A
X4K-Z1U-U8011-A1	X4K-Z1U-U9011-A1	None	X4K-Z1U-B1011-A1	X4K-Z1U-B2011-A1
X4H-Z1U-U801-US	X4H-Z1U-U901-US	None	X4H-Z1U-B101-US	X4H-Z1U-B201-US

X4H-Z1U-U801-AU	X4H-Z1U-U901-AU	None	None	None
X4H-Z1J-U801-UK	X4H-Z1J-U901-UK	None	None	None
X4H-Z1J-U801-EU	X4H-Z1J-U901-EU	None	None	None
X4-HMU-U801-A	X4-HMU-U901-A	None	X4-HMU-B101-A	X4-HMU-B201-A
X4H-HMU-U801-US	X4H-HMU-U901-US	None	X4H-HMU-B101-US	X4H-HMU-B201-US
X4-A1U-U805	X4-A1U-U905	None	X4-A1U-B105	X4-A1U-B205
X4-A1U-U801-A	X4-A1U-U901-A	None	X4-A1U-B101-A	X4-A1U-B201-A
X4-A1J-U805	X4-A1J-U905	None	X4-A1J-B105	X4-A1J-B205
X4-A1J-U801-W	X4-A1J-U901-W	None	None	None

Table 5: Affected OEM Product

EOL Part Number	HSPA+ Replacement	Gobi 4G LTE Replacement	Sprint 1xRTT Replacement	Verizon 1xRTT Replacement
70001657-C25	OEM SKU - See Digi Sales Rep for Replacement			
70002511	OEM SKU - See Digi Sales Rep for Replacement			
70002506	OEM SKU - See Digi Sales Rep for Replacement			
70002504	OEM SKU - See Digi Sales Rep for Replacement			
70002503	OEM SKU - See Digi Sales Rep for Replacement			
70002496	OEM SKU - See Digi Sales Rep for Replacement			
70002493	OEM SKU - See Digi Sales Rep for Replacement			
70002462	OEM SKU - See Digi Sales Rep for Replacement			
70002446	OEM SKU - See Digi Sales Rep for Replacement			
70001702	OEM SKU - See Digi Sales Rep for Replacement			
70001697	OEM SKU - See Digi Sales Rep for Replacement			
70001687	OEM SKU - See Digi Sales Rep for Replacement			
70001680	OEM SKU - See Digi Sales Rep for Replacement			
70001665	OEM SKU - See Digi Sales Rep for Replacement			

70001657	OEM SKU - See Digi Sales Rep for Replacement			
70001656	OEM SKU - See Digi Sales Rep for Replacement			
70001655	OEM SKU - See Digi Sales Rep for Replacement			
70001640	OEM SKU - See Digi Sales Rep for Replacement			

Table 6: ConnectWAN & Specialty Items and Replacement Product

EOL Part Number	HSPA+ Replacement	Gobi 4G LTE Replacement	Sprint 1xRTT Replacement	Verizon 1xRTT Replacement
70001646	None	None	None	None
70001644	None	None	None	None
70001643	None	None	None	None
CP-MOD-G3K1	None	None	None	None
CP-MOD-G3K1-50	None	None	None	None
CP-MOD-G3K2	None	None	None	None
DC-WAN-U801-W	DC-WAN-U901-W	None	None	None
DC-WAN-U801-A	DC-WAN-U901-A	None	DC-WAN-B101-A	DC-WAN-B201-A
DC-WAN-U801	None	None	None	None