



Product Change Notice

Micron PCN: 30958
 Date: 6/30/2013

Type of Change:	End of Life	
Title of Change:	P806 Wireless NOR Flash L18/M18 Family 65nm (1Gb, 512Mb, 256Mb and 128Mb) Termination	
Description of Change:	Micron's part numbers based on P806 Wireless NOR Flash L18/M18 family (65nm) are being discontinued with no replacements.	
Reason for Change:	Product termination	
Contact Information:	<u>Marketing Contact</u> ANTONIO RUSSO ARUSSO@MICRON.COM Micron Semiconductor Italia	<u>Engineering Contact</u> GIOVANNI MESSINA GMESSINA@MICRON.COM Micron Semiconductor Italia
	FRANCESCA CANALI FCANALI@MICRON.COM Micron Semiconductor Italia	
	MICHAEL CHOI MICHAELCHOI@MICRON.COM Micron Semi Korea Co. Ltd	
	DONOVAN HWANG DHWANG@MICRON.COM Micron Semiconductor Prds	
	KAZUYUKI TANAKA KATANAKA@MICRON.COM Micron Japan Ltd.	

Product Affected: Micron's part numbers based on P806 Wireless NOR Flash L18/M18 family (65nm)

Affected Micron Part Numbers

PF58F0033M0Y1BGA	PF48F5000M0Y1BEA	PF38F4050M0Y0QFB
PF38F6070M0Y3DEA	PF48F5000M0Y1BEB	PF48F4000M0Y0CEA
PF48F6000M0Y1BHA	PF38F5070L0Y3AEA	PF38F3070M0Y1EE
PF58F0121M0Y0BFA	PF38F5070L0Y3AEB	PF38F3070M0Y1EEB
PF58F0121M0Y0BFB	PF38F5060L0Y3AFA	PF38F3060M0Y1EHA
PF38F5060M0Y4DFA	PF38F5060L0Y3AFB	PF38F3060M0Y1EHB
PF38F5060M0Y4DFB	PF38F4060M0Y4DEA	PF38F3050M0Y3DEA
PF38F5060M0Y3CFA	PF38F4060M0Y4DEB	PF38F3050M0Y3DEB
PF38F5060M0Y3DK	PF38F4060M0Y3DF W3	PF38F3050M0Y1YEA
PF38F5060M0Y0CHA	PF38F4060M0Y1YEA	PF38F3050M0Y1YEB
PF38F5060M0Y0CHB	PF38F4060M0Y0YEA	PF38F3040M0Y3DFA
PF38F5060M0Y0CFA	PF38F4050M0Y3DEA	PF38F3040M0Y3DFB
PF38F5060M0Y0CFB	PF38F4050M0Y3DEB	

Micron Sites Affected: All Sites

Last Time Buy Date: 31-Dec-2013

Last Time Ship Date: 30-Jun-2014

Note: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change