

Phoenix Contact Inc.
P.O. BOX 4100
Harrisburg, PA 17111-0100
Phone: 717-944-1300

Product Change Notification

PCN-IFC-8246-2022

Business Unit	Product Line Code	Type of Change	Action	Date of Issue
IFC - Industrial Field Connectivity	BF2	Product Change Notification	Notify Distributors and Field	9/27/2022

The following Phoenix Contact products have been modified. Existing specifications will be met or exceeded. Please review and acknowledge this document and inform your personnel as needed.

Description for Product Change Notification

The M12 connectors with push-in (push-lock) are changing from SPEEDCON to M12 standard. This change affects the entire SACC push-lock portfolio. This change is a strategic decision and will be implemented successively for all SACC's with SPEEDCON. In the future, the SPEEDCON connection will be replaced by the new standardized M12 push-pull connection in accordance with IEC 61076-2-010. From the user's point of view, there are no technical disadvantages (connection, dimensions, etc.). The approvals, such as UL, will also remain unchanged.

Stock Status

Can existing stock still be used?	Yes
Is mixture of stock acceptable?	Yes

Transaction Dates

Date modification goes into effect from Germany:	1/1/2023
Expected first shipment (from Phoenix Contact) of the modified products(s):	1/1/2023



Phoenix Contact Inc.
P.O. BOX 4100
Harrisburg, PA 17111-0100
Phone: 717-944-1300

Product Change Notification

Previous Product	New Product
	
	



Phoenix Contact Inc.
P.O. BOX 4100
Harrisburg, PA 17111-0100
Phone: 717-944-1300

Product Change Notification

Should you have any issues with the timeline or content of this product change, please contact Phoenix Contact using the information below. Customers should acknowledge receipt of the PCN within 30 days of delivery of the PCN; provided, however, that the failure to acknowledge receipt does not affect the product change or the effective date thereof.

Contact Info:

Yogi Patel
ypatel@phoenixcontact.com

Thank you,

Jeremy Andrews

Product Marketing Manager

Product Change Notification

Part #	Type Description
1012968	SACC-M12FS-5PL M DN
1012969	SACC-M12FR-5PL M DN
1424652	SACC-M12FS-5PL M
1424653	SACC-M12FR-5PL M
1424655	SACC-M12FS-4PL M
1424656	SACC-M12FR-4PL M
1424660	SACC-M12FS-5PL SH
1424661	SACC-M12FR-5PL SH
1424664	SACC-M12FSB-5PL SH
1424665	SACC-M12FRB-5PL SH
1424668	SACC-M12FS-4PL SH
1424669	SACC-M12FR-4PL SH
1424672	SACC-M12FS-5PL SH DN
1424673	SACC-M12FR-5PL SH DN
1424676	SACC-M12FSB-5PL SH IB
1424677	SACC-M12FRB-5PL SH IB
1424680	SACC-M12FSB-2PL SH PB
1424681	SACC-M12FRB-2PL SH PB
1424683	SACC-M12FSD-4PL SH PN
1424685	SACC-M12FRD-4PL SH PN
1424696	SACC-M12FSB-3PL SH PB
1424698	SACC-M12FRB-3PL SH PB
1424700	SACC-M12FS-4PL SH CCL
1012966	SACC-M12MS-5PL M DN
1012967	SACC-M12MR-5PL M DN
1424649	SACC-M12MS-5PL M
1424651	SACC-M12MR-5PL M
1424654	SACC-M12MR-4PL M
1424657	SACC-M12MS-4PL M
1424658	SACC-M12MS-5PL SH
1424659	SACC-M12MR-5PL SH
1424662	SACC-M12MSB-5PL SH
1424663	SACC-M12MRB-5PL SH
1424666	SACC-M12MS-4PL SH
1424667	SACC-M12MR-4PL SH
1424670	SACC-M12MS-5PL SH DN
1424671	SACC-M12MR-5PL SH DN
1424674	SACC-M12MSB-5PL SH IB
1424675	SACC-M12MRB-5PL SH IB
1424678	SACC-M12MSB-2PL SH PB
1424679	SACC-M12MRB-2PL SH PB
1424682	SACC-M12MSD-4PL SH PN
1424684	SACC-M12MRD-4PL SH PN
1424695	SACC-M12MSB-3PL SH PB
1424697	SACC-M12MRB-3PL SH PB
1424699	SACC-M12MS-4PL SH CCL