

DS36C278TMX/NOPB SN65HVD3088EDR Q	null
DS36C279M/NOPB SN65HVD3088ED Q	null
DS36C279MX/NOPB SN65HVD3088EDR Q	null
DS485M SN65HVD485ED Q	null
DS485M/NOPB SN65HVD485ED Q	null
DS485MX/NOPB SN65HVD485EDR Q	null
DS485N/NOPB SN65HVD485EP Q	null
DS485TM SN65HVD485EDR Q	null
DS485TM/NOPB SN65HVD485EDR Q	null
DS485TMX/NOPB SN65HVD485EDR Q	null
DS75176BM SN65176BD Q	null
DS75176BM/NOPB SN65176BD Q	null
DS75176BMX/NOPB SN65176BDR Q	null
DS75176BN/NOPB SN65176BP Q	null
DS75176BTM SN65176BDR Q	null
DS75176BTM/NOPB SN65176BDR Q	null
DS75176BTMX/NOPB SN65176BDR Q	null
DS75176BTN/NOPB SN65176BDR Q	null
DS8921ATM SN65HVD485EDR Q	null
DS8921N/NOPB SN65HVD485EP Q	null
DS8922AM/NOPB None NA	null
DS8922AMX/NOPB None NA	null
DS8923AM/NOPB None NA	null
DS8923AMX/NOPB None NA	null
DS8923AN/NOPB None NA	null
DS89C21TM None NA	null
DS89C21TMX None NA	null
DS9637ACM/NOPB UA9637ACD Q	null
DS9638CM/NOPB UA9638ACD Q	null
DS9638CMX/NOPB UA9638ACDR Q	null
HPC46003V20/NOPB MSP430G2302IPW20R F	null
LF411ACN/NOPB LF411CP Q	null
LF411CN/NOPB LF411CP S	null
LF442ACN/NOPB TL032CP Q	null
LF442CN/NOPB TL032CP Q	null
LM1973M/NOPB LM1972M/NOPB F	null
LM2984CT/NOPB TPS51103DRCR P	null
LM301AN/NOPB TL031CO Q	null
LM3046M/NOPB None NA	null
LM3046MX/NOPB None NA	null
LM329DZ/NOPB LM4040DIZ-5.0/NOPB F	null
LM3433SQ/NOPB None NA	null
LM3434SQ/NOPB None NA	null
LM346M/NOPB PGA280AIPWR F	null
LM346MX/NOPB PGA280AIPWR F	null
LM348M/NOPB LM348D S	null
LM348MX/NOPB LM348DR S	null
LM348N/NOPB LM348N S	null
LM4250CM/NOPB PGA204AU F	null
LM4250CMX/NOPB PGA204AU/1K F	null
LM4250CN/NOPB PGA204AP F	null
LM4802BLQ/NOPB TPA2100P F	null
LM5025DMTC/NOPB LM5025SD/NOPB S	null
LM5027ASQ/NOPB LM5025ASD/NOPB S	null
LM5037MT/NOPB LM25037MT/NOPB F	null
LM556CM/NOPB NE556D S	null
LM556CMX/NOPB NE556DR S	null
LM556CN/NOPB NE556N S	null
LM611CM/NOPB LM10CWM/NOPB P	null
LM613IWM TSM102AIPW F	null
LM613IWM/NOPB TSM102AIPW F	null
LM614CWM/NOPB TSM104WAID S	null
LM6181IM-8/NOPB THS3120ID Q	null
LM6181IMX-8/NOPB THS3120ID Q	null
LM6181IN/NOPB THS3120ID P	null
LM723CN/NOPB LM723CH/NOPB P	null
LM79M12CT/NOPB LM2990T-12/NOPB Q	null
LMC6572BIMX/NOPB LMC6022IMX/NOPB Q	null
LMC8101MM/NOPB LMC7101AIM5/NOPB P	null
LME49710HA/NOPB OPA1611AID F	null
LME49710MAX/NOPB OPA1611AIDR F	null

LME49710NA/NOPB OPA1611AID F	null
LME49725MA/NOPB OPA1622AID F	null
LMP8671MA/NOPB LME49710MAX/NOPB Q	null
LMS202EIM/NOPB TRS232EID Q	null
LMS202EIMX/NOPB TRS232EIDR Q	null
SM72375MME/NOPB LMC6772QMMX/NOPB P	null
TP3054N/NOPB None NA	null
TP3054WM/NOPB None NA	null
TP3054WMX/NOPB None NA	null
TP3057WM/NOPB None NA	null
TP3067WM/NOPB None NA	null
TP3070V-G/NOPB None NA	null
TP3070V-XG/NOPB None NA	null
TP3071N-G/NOPB None NA	null
DS2003TMX ULN2003AID Q	null
DS3691MX/NOPB None NA	null
DS3695ATMX/NOPB SN65HVD485EDR Q	null
DS481TM/NOPB SN65HVD485EDR Q	null
DS481TMX/NOPB SN65HVD485EDR Q	null
DS9637ACMX/NOPB UA9637ACDR Q	null
LM432MAX/NOPB TL103WIDR S	null
LM5025DMTCX/NOPB LM5025SDX/NOPB S	null
LM5027AMH/NOPB LM5025AMTC/NOPB F	null
LM611IM/NOPB LM10CWM/NOPB P	null
LMC6572AIM/NOPB TPS7A91 F	null
LMC6572BIM/NOPB LMC6022IM/NOPB Q	null
LMC6574BIM/NOPB LMC6024IM/NOPB Q	null
LMC8101MMX/NOPB LMC7101AIM5X/NOPB P	null
LMP8674MA/NOPB OPA1604AIDR Q	null
LMS202ECM/NOPB TRS232EID Q	null
LMS202ECMX/NOPB TRS232EIDR Q	null
SM72375MM/NOPB LMC6772QMM/NOPB P	null
SM72375MMX/NOPB LMC6772QMMX/NOPB P	null
TP3403V/NOPB None NA	null

Technical details of this Product Change follow on the next page(s).

PDN Number:	20170721000	PDN Date:	Aug 7, 2017
Title:	Discontinuance of Select Devices Sourced in GFAB		
Customer Contact:	PCN Manager	Dept:	Quality Services
Last date to order:	Aug 7, 2018	Last date to ship:	Feb 7, 2019
Change Type:	Product Discontinuance - End Of Life		
Product Discontinuance Notification Details			
Description of Withdrawal/Discontinuance:			
Texas Instruments, Incorporated (TI) is announcing the discontinuance of select devices sourced in GFAB. A lifetime buy is being offered with the date given above. Recommended replacements are being offered on most devices as shown in page 2 of this document.			
NOTE: There are no samples offered for withdrawn/obsolete products. If you have any questions, please contact your local sales representative.			
Reason for Withdrawal/Discontinuance:			
GFAB site closure			
Product Affected:			
Please see affected device list on page 2.			

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com