

CUSTOMER	CUSTOMER DRAWING OR PART NUMBER	REV. NO.	TODAYS DATE 2/1/2019
JKL PART NUMBER(s) 7583	PART DESCRIPTION T-1 1/4 Bi Pin Lamp, 5V	Part Family T-1 1/4 Bi Pin	
JKL CONTACT NAME	PHONE	EMAIL:	

REASON FOR NOTICE: This lamp is no longer being produced.
--

<b>Obsolete Item:</b> 7583 This lamp is rated at: 5V .060A .050 MSCP This lamp is .600" MOL	<b>Suggested Replacement Item:</b> 7362 The suggested replacement lamp is rated at: 5V .115A .150 MSCP (brighter)  This lamp is .625" MOL (Slightly taller) The pin spacing is the same
---	---