



Product Change Notification (PCN)


PCN Number	506164	Date Issued	October 09, 2018
Reason for Change	Capacity change or tool replacement		
Change Type Description	This letter is to inform you that another set of tooling is being added to meet the current and future demands of this product. There will be no changes in the fit, form or function from the additional tooling when compared to the current tooling.		
Reason for Short Notice	Special Request		
Assessment of Change	Test report/Specification Test Report		
Internal Molex Qualification Date	October 19, 2018		
Sample Availability Date (Changed Part)	October 19, 2018		
Planned Implementation Date	October 26, 2018		
Method of Identifying Change	Factory order number		

RELEASED

Before Change

After Change

- Difference in pin tips



New pin tip

Existing pin tip

Overview

- Molex are looking at introducing a second source for the bandolier pins used on the QF50 flex header assemblies.
- Product Impact
 - No impact to the product
 - Slight difference in tip profile as shown in the before picture
- Series Number Impacted
90571, 90572, 90607, 90663
- Qualification Reports and samples available upon request



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:506164**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com

Molex Part #

905711101

905711141

905711161

905711201

905721101

906631101

906631101

906631102

906631141

906631142

906631161

906631201

906631202

906631261

906631262

906631302

906631341

906631342

906631402

906631501

906631601

906633102

906633141

906633161

906633163

906633201