

## PRODUCT CHANGE NOTIFICATION

**TO:** ALL AFFECTED CUSTOMERS

**FROM:** QUALTEK ELECTRONICS

**DATE:** February 23, 2021

**CLASSIFICATION OF CHANGE:** FAD1-04020 SERIES REMOVAL OF SLEEVE BEARING

---

**THE FOLLOWING PART NUMBERS ARE OBSOLETE:**

PART NUMBER	RECOMMENDED PART NUMBER REPLACEMENT
FAD1-04020BSAW11	FAD1-04020BHAW11
FAD1-04020BSLW11	FAD1-04020BHLW11
FAD1-04020BSMW11	FAD1-04020BHMW11
FAD1-04020BSHW11	FAD1-04020BHHW11
FAD1-00420CSAW11	FAD1-04020CHAW11
FAD1-04020CSLW11	FAD1-04020CHLW11
FAD1-04020CSMW11	FAD1-04020CHMW11
FAD1-00420CSHW11	FAD1-04020CHHW11
FAD1-04020CSJW11	FAD1-04020CHJW11
FAD1-04020DSAW11	FAD1-04020CHKW11
FAD1-04020DSLW11	FAD1-04020DHLW11
FAD1-04020DSMW11	FAD1-04020DHMW11
FAD1-04020DSHW11	FAD1-04020DHHW11

THE RECOMMENDED REPLACEMENTS UTILIZE OUR HYDRO DYNAMIC BEARING INSTEAD OF SLEEVE BEARING. THIS BEARING STRUCTURE PROVIDES A LONGER LIFE 50K HOURS VS 30K HOURS WHILE ALSO PROVIDING SIMILAR LEVELS OF NOISE AND PERFORMANCE.

**LAST TIME BUY:** NONE.

**CONTACT INFORMATION:** PLEASE CONTACT QUALTEK ELECTRONICS CUSTOMER SERVICE FOR AVAILABILITY.

PHONE: 440-951-3300

FAX: 440-951-7252