



t-Global Technology (Europe and North America) Ltd
Unit 1 &2 Cosford Business Park
Central Park
Lutterworth
LE17 4QU
UK
sales@tglobaltechnology.com
t: +44 (0)1455 553 510

Part Change Notification Number: TGEANA_PCN_0008_Digi-Key


Date: 13th March 2020

Parts Affected:


<u>Manufacturer P/N</u>	<u>Digi-Key P/N</u>
TG-CJ-LI-20-20-6-PF	1168-2130-ND
TG-CJ-LI-32-32-6-PF	1168-2132-ND
TG-CJ-LI-30.5-30.5-6-PF	1168-2131-ND
TG-CJ-LI-12-12-10-PF	1168-2129-ND
TG-CJ-LI-60-60-15-PF	1168-2134-ND
TG-CJ-LI-43-43-6-PF	1168-2134-ND
TG-CJP-12-LI98	1168-2211-ND
XLI98-20-2.25-P	1168-1970-ND
XLI98-10-2.25-P	1168-1968-ND

Reason: Disruption in supply of liner material due to COVID-19.

Description: Due to the situation regarding COVID-19 in mainland China, our usual supplier cannot currently produce and continue to supply the original red liners for the Li98 found on our ceramic assemblies. In response to this, Li98 0.25mm will now have a blue liner as shown below. The change of liner colour does not affect the function of the product in any way.



Original Li98 – 0.25mm red



New Li98 - 0.25mm

Should you require more details or wish to discuss this please do not hesitate to contact us at sales@tglobaltechnology.com.

Effective date: Immediately

Approved By: Duncan Bell, General Manager