



Product Change Notification

Date Issued :	October 10, 2022	PCN Number :	512765
Reason for Change :	Packaging Method/Quantity Changing		
Description of Change :	This notification is to inform you about part(s) listed in this notice that will undergo changes for the new delivery unit. No changes will be made to the product as a result of this change.		
Reason for Short Notice :	Corrective Actions		
Assessment of Change :	No change to parts - Form/Fit/Function		
Planned Implementation Date :	November 01, 2022		
Sample Availability Date:	October 31, 2022		
Internal Molex Qualification Date :	October 28, 2022		
Last date to request Samples by Customer :	October 28, 2022		

Before Picture

- Change of packaging delivery unit and standard quantity needed regarding Molex terminal block part number 395056006



After Picture

Overview

- To align the delivery unit quantities in our system, Molex is updating the delivery unit for the product identified in this change.
- Product Impact
 - No impact to form, fit or function of the products in question.
- Part Number Impact
 - 395056006

RELEASED

You may address inquiries regarding this PCN by clicking on the below link
mailto:pcn_coordinator@molex.com?subject=PCN_Notification:512765
or contact your Local Sales Engineer.

Note: While responding, please retain " PCN Notification : **PCN Notification: 512765** " in the e-mail Subject line for faster response.

[Molex, LLC](#)
2222 Wellington Court
Lisle, IL 60532
TEL (800) 786-6539
www.molex.com

Molex Part Number	Current Standard Pack Quantity (DU)	Current Minimum Order Quantity(MLQ)	New Standard Pack Quantity (DU)	New Minimum Order Quantity(MLQ)
395056006	2,304	4,608	2,340	4,680