



Product Change Notification - SYST-09IBIE964

Date:

10 Oct 2019

Product Category:

Ultrasound Transmitter Pulsar ICs

Affected CPNs:



Notification subject:

Data Sheet - HV7351 Data Sheet

Notification text:

SYST-09IBIE964

Microchip has released a new Product Documents for the HV7351 Data Sheet of devices. If you are using one of these devices please read the document located at [HV7351 Data Sheet](#).

Notification Status: Final

Description of Change: 1) Updated Figure 3-3. 2) Updated Table 3-2 and Table 3-3.

Impacts to Data Sheet: None

Reason for Change: To Improve Manufacturability

Change Implementation Status: Complete

Date Document Changes Effective: 10 Oct 2019

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachment(s):

[HV7351 Data Sheet](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

HV7351K6-G