

## Global Change Notification (GCN)

Product Family	MX150	10618037
		GCN Number
Series	33471-03** and 33471-06**	December 18, 2013
		Date Issued
Reason For Change	New, Modified, Or Replacement Tooling	
Change Description	The tools that produce 1x3 and 1x6 ring seals have reached end of life and are now being replaced. The color will remain "burnt orange". PPAP available upon request.	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception	New Capacity	
Assessment Of Change (How Product Will Be Qualified & Validated)		
Internal Molex Qualification Date (Planned Date Information Available)	April 01, 2014	
Sample Availability Date (Changed Part)	April 01, 2014	
Date of Implementation	April 01, 2014	
Method of Identifying Change	NA	
Recommended Replacement Parts		
Last Time Buy Date for Obsolete Parts		
Last Time Ship Date for Obsolete Parts		

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	QuiNann Lim	QuiNann.Lim@molex.com	+31-40-295-8472
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

**Molex, Inc.**  
 2222 Wellington Court  
 Lisle, IL 60532  
 TEL: 630-969-4747  
[www.molex.com](http://www.molex.com)