



CUSTOMER OPERATIONS
 160 RIO ROBLES
 SAN JOSE, CA 95134

PDN #: M000789

DATE: 15-Dec-2014

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	MAX98355EVKIT#	MAX98357EVSYS#WLP	15-Dec-2014	14-Dec-2016	The eval kit is no longer supported
Discontinuance	MAX98356EVKIT#	MAX98358EVSYS#TQFN	15-Dec-2014	14-Dec-2016	The eval kit is no longer supported
Discontinuance	MAX15301AA01+CK	MAX15301AA02+CJK	18-Jun-2015	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX15301AA01+TCK	MAX15301AA02+TCJK	18-Jun-2015	17-Jun-2017	Part can no longer be manufactured
Discontinuance	MAX15303ETL+	N/A	18-Jun-2015	17-Jun-2017	The part was not released
Discontinuance	SD788+	MAX21004/V+	18-Jun-2015	17-Jun-2017	Part can no longer be manufactured
Discontinuance	SD788+T	MAX21004/V+	18-Jun-2015	17-Jun-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 15-Jan-2015