



# Product Change Notification

## TE Connectivity

Product Change Notification: P-16-013977

PCN Date: 20-DEC-16

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:  
 Manufacturing Location Change of Menlo Park Appliances Tubing ES2000 Products

Description of Changes  
 Manufacturing location change. Following Part Numbers will be transferred from Menlo Park to Shanghai. This Product Notification is to inform our customers that TE Connectivity (TE) will also be moving the manufacturing of ES2000 products to the Shanghai tubing facility in China. The Shanghai facility is an already established Heat Shrinkable Tubing ( Tubing or Products ) manufacturing site. - since 1996.  
 Other attachments:  
[ES2000 PCN Information](#)  
[ES2000 Affected Part Numbers & Packaging details](#)

Reason for Changes:  
 Dear Customer, we hereby inform you about a transfer of processes. The transfer follows a strict procedure, which fully maintains quality, ability to supply and form-fit function of the concerned products. The new manufacturing location operates under a certified quality management system in accordance with standard automotive requirements. Upon request, a PPAP Level 2 will be available. This notification is to inform our customers that TE Connectivity is closing our Menlo Park facility in USA and moving the production to our Shanghai facility in China. The receiving facility is already an established Heat Shrinkable Tubing ( Tubing or Products ) manufacturing site - since 1996. See attached document.  
 Estimated Dates:  

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	21-MAR-2017
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	21-MAR-2019

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">063725P017</a>	NO			"5-1190481-7", "ES2000-NO.2-B9-0-40MM"			
<a href="#">063725P022</a>	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
<a href="#">121397P018</a>	NO			"3-1190883-8", "ES2000-NO.3-B8-0-50MM"			
<a href="#">121397P024</a>	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
<a href="#">130599P006</a>	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
<a href="#">829131P021</a>	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
<a href="#">829131P026</a>	NO			"8-1196474-3", "ES2000-NO.1-C1-0-25MM"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">063725P017</a>	NO			"5-1190481-7", "ES2000-NO.2-B9-0-40MM"			
<a href="#">063725P022</a>	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">121397P018</a>	NO			"3-1190883-8", "ES2000-NO.3-B8-0-50MM"			
<a href="#">121397P024</a>	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
<a href="#">130599P006</a>	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
<a href="#">829131P021</a>	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
<a href="#">829131P026</a>	NO			"8-1196474-3", "ES2000-NO.1-C1-0-25MM"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">063725P017</a>	NO			"5-1190481-7", "ES2000-NO.2-B9-0-40MM"			
<a href="#">063725P022</a>	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
<a href="#">121397P018</a>	NO			"3-1190883-8", "ES2000-NO.3-B8-0-50MM"			
<a href="#">121397P024</a>	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
<a href="#">130599P006</a>	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
<a href="#">829131P021</a>	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
<a href="#">829131P026</a>	NO			"8-1196474-3", "ES2000-NO.1-C1-0-25MM"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">063725P022</a>	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
<a href="#">121397P024</a>	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
<a href="#">130599P006</a>	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
<a href="#">829131P021</a>	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">063725P022</a>	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
<a href="#">121397P024</a>	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
<a href="#">130599P006</a>	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
<a href="#">829131P021</a>	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substib.lte Part Number	Substitute Alias Part Number(s)	Description Of Difference
				7-1196474-9", "ES2000-NO.1-CI-STK"			