

MACOM Technology Solutions Inc.
1500 Hughes Way, Suite C-100
Long Beach, California 90810
+1 (310) 320-6160
www.macom.com



October 18, 2016

Digi-Key Corporation
701 Brooks Ave South
Thief River Falls, Minnesota 56701

ATTN: Quality/Purchasing Manager

Subject: Product Discontinuance Notice

PCN #: PCN-00933

Dear Valued Customer:

In accordance with MACOM Technology Solutions' customer product discontinuance policy, this communication is to inform you that MACOM Technology Solutions is discontinuing the part number(s) listed below. The reason for discontinuance is due to rising costs associated with supporting products based on old technologies. No replacement part number is anticipated at this time. You are receiving this notification because you have purchased one or more of the following part numbers in the past two years.

Affected Part Numbers: MAPM-020512-010C00, MAPM-020512-040C01,
MAPM-020512-040C00, MAPM-030400-010C00, PHA4000-1, PHA4000-2,
PHA4006-1, PHA4006-2

We are offering an opportunity to place last time buy orders for these products until current inventory is exhausted. Orders must be received by April 28, 2017 with delivery scheduled by October 28, 2017.

Please contact your local sales representative if you have any questions or require additional information.

Sincerely,

Greg French
Sr. Product Marketing Manager
MACOM Technology Solutions, Inc.
Tel: +1 (310) 357-2311
Email: gregory.french@macom.com