

SPL -Series Suggested Replacements

1. These are **NOT** direct 'drop in' replacements. These are our closest 'ELECTRICAL' replacements. The mounting and input and output connections will be different. (MAP's are smaller than SPL's. MAP's have Molex *and* Screw terminals. SPL's have screw terminal blocks only)
2. In general, the MAP-Series has better EMI, Line/Load regulation, lower minimum load requirements and auto ranging inputs over the SPL-Series.
3. Please consult our catalog or use "PROBE" on our web site to determine if this product is suitable for your application.
4. Please feel free to contact our technical support group at ext. 4117 or 4159 to discuss your requirements.

SPL	MAP
SPL40-1005	MAP42-1005*
SPL40-1012	MAP42-1012*
SPL40-1024	MAP42-1024*
SPL40-4000	MAP55-4000
 SPL50-3200	 MAP40-3100 or MAP55-4000
SPL53-1005	MAP110-1005* or MAP80-1005
SPL53-1012	MAP110-1012* or MAP80-1012
SPL53-1024	MAP110-1024* or MAP80-1024
SPL53-4000	MAP110-4000* or MAP80-4000
SPL53-4101	MAP110-4001* or MAP80-4001
SPL53-4102	MAP110-4002* or MAP80-4002
 SPL130-1005	 MAP130-1005
SPL130-1012	MAP130-1012
SPL130-1024	MAP130-1024
SPL130-4000	MAP130-4000
SPL130-4100	MAP130-4002
SPL130-4101P	MAP130-4001
SPL130-4102P	MAP130-4000
 SPL175-4000R	 No Close Replacement. Contact Technical Support
SPL175-4100	No Close Replacement. Contact Technical Support
SPL175-4200	No Close Replacement. Contact Technical Support
SPL175-4300	No Close Replacement. Contact Technical Support
SPL200-4000P	No Close Replacement. Contact Technical Support
SPL200-5100P	No Close Replacement. Contact Technical Support
SPL200-5200P	No Close Replacement. Contact Technical Support

*Molex Terminals Only.

11-17-98