



Product Change Notification

Date Issued :	July 29, 2022	PCN Number :	512455
Reason for Change :	Retraction		
Description of Change :	This notification is to advise you of a modification to a previously issued PCN. Please refer to the information below for details regarding the amendment.		
Assessment of Change :	Reliability Test Report/s		
Planned Implementation Date :	July 29, 2022		
Sample Availability Date:	July 27, 2022		
Internal Molex Qualification Date :	July 27, 2022		
Last date to request Samples by Customer :	July 28, 2022		
Traceability Code Markings / Date :	Lot information on label		

Before Picture

Retraction PCN for PCN#512421

- We inform that PCN#512421 will be retracted because we found target product of PCN#512421 - #533146065 - had been obsoleted under PCN#508518 on Feb 28th, 2021.
- This retraction is effective immediately.

After Picture


Reference) PCN#512421 CFD information

Background of This PCN


- As we informed by the News Release on February 2, 2022, Toray Industries, one of Molex's resin suppliers, announced it had improperly identified certain resin products as receiving certification from Underwriters Laboratories (UL), a global third-party safety science organization headquartered in the United States. <https://www.toray.com/global/news/details/20220131151731.html>
- As previously noted, products sold to you by Molex contain resins from Toray Industries, Inc. (collectively, the "Affected Toray Resins") that were inappropriately certified by Underwriters Laboratories (UL). Molex has since learned the Affected Toray Resins have their UL certifications revoked on March 31, 2022.
- Due to the reasons noted above, Molex has made the decision to stop shipping products that use the Affected Toray Resins as of March 8, 2022 unless an accommodation can be reached.
- This PCN is to inform you about the change from Toray resin to other UL94 V-0 resin, which we will implement to resume stable supply of these products.

Change Overview

- Change a resin material for 53314-6065 Housing




Parts that change the resin
HEADER HSG



Contents	Current	New
Resin	TORAY PA66	SABIC PBT

- This SABIC PBT has already been used in the 53314 gold-plated series (55458 series) and has proven to be functionally acceptable.
- Product Impact: No impact to fit, form or function
- Part Number Impact: 533146065
- Identification: For the first 6 months of the production start by the alternative material, we will add "M" at the end of Traceability number (see the picture right) of the label to identify products made from alternative materials.



Molex Confidential Information
© 2016 Molex - All Rights Reserved. Unauthorized Reproduction/Distribution is Prohibited.

molex

Molex Confidential Information
© 2016 Molex - All Rights Reserved. Unauthorized Reproduction/Distribution is Prohibited.

molex

RELEASED

You may address inquiries regarding this PCN by clicking on the below link
mailto:pcn_coordinator@molex.com?subject=PCN_Notification:512455
 or contact your Local Sales Engineer.

Note: While responding, please retain " PCN Notification : **PCN Notification: 512455** " in the e-mail Subject line for faster response.

Molex, LLC
 2222 Wellington Court
 Lisle, IL 60532
 TEL (800) 786-6539
www.molex.com