

<b>Notification Number:</b>	20160229000	<b>Notification Date:</b>	03/14/2016
<b>Title:</b>	Datasheet update for LM3880/LM3880-Q1		
<b>Customer Contact:</b>	<a href="#">PCN Manager</a>	<b>Dept:</b>	Quality Services
<b>Change Type:</b>			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Materials
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Process

### Notification Details

#### Description of Change:

Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as seen in the change revision history below:



#### LM3880, LM3880-Q1

SNVS451K –AUGUST 2006–REVISED FEBRUARY 2016

[www.ti.com](http://www.ti.com)

#### Changes from Revision J (December 2014) to Revision K

Page

- Added cross references to timing diagrams ..... 3
- Changed Handling Ratings to ESD Ratings and moved storage temperature to Absolute Maximum Ratings ..... 5
- Removed "Customized Timing and Sequence" section ..... 13

The datasheet number will be changing.

Device Family	Change From:	Change To:
LM3880/LM3880-Q1	SNVS451J	<b>SNVS451K</b>

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/product/lm3880-q1>

#### Reason for Change:

- Remove Section
- Minor editorial change to help clarify info for reader

#### Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

No anticipated impact. This is a specification change announcement only. There are no changes to the actual device

#### Changes to product identification resulting from this notification:

None.

#### Product Affected:

LM3880MF-1AA	LM3880MFE-1AD/NOPB	LM3880QMF-1AB/NOPB	LM3880QMFE-1AF/NOPB	
LM3880MF-1AA/NOPB	LM3880MFE-1AE/NOPB	LM3880QMF-1AC/NOPB	LM3880QMF-1AA/NOPB	
LM3880MF-1AB/NOPB	LM3880MFE-1AF/NOPB	LM3880QMF-1AD/NOPB	LM3880QMF-1AB/NOPB	
LM3880MF-1AC/NOPB	LM3880MFX-1AA/NOPB	LM3880QMF-1AE/NOPB	LM3880QMF-1AC/NOPB	
LM3880MF-1AD/NOPB	LM3880MFX-1AB/NOPB	LM3880QMF-1AF/NOPB	LM3880QMF-1AD/NOPB	
LM3880MF-1AE/NOPB	LM3880MFX-1AC/NOPB	LM3880QMFE-1AA/NOPB	LM3880QMF-1AE/NOPB	
LM3880MF-1AF/NOPB	LM3880MFX-1AD/NOPB	LM3880QMFE-1AB/NOPB	LM3880QMF-1AF/NOPB	
LM3880MFE-1AA/NOPB	LM3880MFX-1AE/NOPB	LM3880QMFE-1AC/NOPB		
LM3880MFE-1AB/NOPB	LM3880MFX-1AF/NOPB	LM3880QMFE-1AD/NOPB		
LM3880MFE-1AC/NOPB	LM3880QMF-1AA/NOPB	LM3880QMFE-1AE/NOPB		

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

<b>Location</b>	<b>E-Mail</b>
USA	<a href="mailto:PCNAmericasContact@list.ti.com">PCNAmericasContact@list.ti.com</a>
Europe	<a href="mailto:PCNEuropeContact@list.ti.com">PCNEuropeContact@list.ti.com</a>
Asia Pacific	<a href="mailto:PCNAsiaContact@list.ti.com">PCNAsiaContact@list.ti.com</a>
Japan	<a href="mailto:PCNJapanContact@list.ti.com">PCNJapanContact@list.ti.com</a>