

**1 Products affected**

Product hierarchy no. *			Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PGU Type				
02	007	013	0000002404	See list below	Appliance outlet	5213

\*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

List of part numbers affected							
6183.0001	6183.0008	6183.0009	6183.0010	6183.0011	6183.0012		

**2 Type of change**

Modification of rating mark


**3 Detailed description of change**

Change of rated current acc. to UL 60320




Old: 21A 125/250V~ new: 20A 250V~

Approvals   shifted


Old marking



New marking



5213 Appliance Outlet					0118.2202	
creation date	created by	release date	released by	notification no.	revision	page
2014-01-15	hotzar	2014-05-01	hotzar	26105	a	1 of 2





**4 Reason of change**

Assignment approval mark to rated current. Rated current adjusted to UL 60320

**5 Released date**

The change will be rolled-out individually by all part numbers affected starting ww 08/2014 and last approx. 9 months.

**6 Impact of change and recommended action**

Form: New current rating according to UL 60320  
 Approvals   shifted  
 Fit: N/A  
 Function: N/A  
 Production Site: N/A  
 Product Label: N/A

**7 Reference Documents / Attachments**

Kind of document	Document number	Remarks
<a href="#">Data Sheet 5213</a>		

5213 Appliance Outlet					0118.2202	
creation date	created by	release date	released by	notification no.	revision	page
2014-01-15	hotzar	2014-05-01	hotzar	26105	a	2 of 2