



## Not Recommended for New Design: Various EYG-E Series Pyrolytic Graphite Sheet SSM Part Numbers

NRFND.PG33.7.6.2021

7.6.2021

|  |  |
|--|--|
| <b>About This Notice:</b>                  | As a result of limited demand, intermittent production and market conditions, various Pyrolytic Graphite Sheet Semi Sealing Material (SSM) are now Not Recommended For New Design. |
| <b>Features:</b>                           |  |
| <b>Effective Date:</b>                     | Immediate  |
| <b>Affected Parts and/or Replacements:</b> | See Attached.  |
| <b>Datasheet(s):</b>                       | See Attached.  |
| <b>Notes:</b>                              |  |

## Panasonic NRFND.PG33.7.6.2021 Affected Parts

| Affected Part Numbers | Suggested Replacement Series |
|-----------------------|------------------------------|
| EYG-E0912XB6D         | No replacement               |
| EYG-E0912XB8D         | No replacement               |
| EYG-E0912XB9D         | No replacement               |
| EYG-E0912XD6D         | No replacement               |
| EYG-E0912XD7F         | No replacement               |
| EYG-E0912XD8D         | No replacement               |
| EYG-E0912XD9D         | No replacement               |
| EYG-E0912XF5F         | No replacement               |