

PRODUCT DISCONTINUATION



PD_137_14

■ Last order:	2015-02-28
■ Last delivery:	2015-08-31

Original: Product Discontinuation N° 137/14 dated 2014-08-18
Update: [SP000745098](#), [SP000745118](#), [SP000753488](#) revoked / New replacement products

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	OPN	Package	Device	Ordering Code	OPN	Package
BB 535 E7779	SP000010380	BB535E7779HTSA1	SOD323	BB 535 E7904	SP000010375	BB535E7904HTSA1	SOD323
BB 535 E7907	SP000010374	BB535E7907HTMA1	SOD323	BB 535 E7904	SP000010375	BB535E7904HTSA1	SOD323
BB 535 E7908	SP000010377	BB535E7908HTSA1	SOD323	BB 535 E7904	SP000010375	BB535E7904HTSA1	SOD323
BB 555-02V H7902	SP000745088	BB55502VH7902XTSA1	SC79	BB 555-02V H7912	SP000745092	BB55502VH7912XTSA1	SC79
BB 565-02V H7902	SP000745098	BB56502VH7902XTSA1	SC79	none			
BB 639 E7907	SP000010400	BB639E7907HTMA1	SOD323	BB 639 E7904	SP000010401	BB639E7904HTSA1	SOD323
BB 639C E7908	SP000010398	BB639CE7908HTSA1	SOD323	BB 639C E7904	SP000010396	BB639CE7904HTSA1	SOD323
BB 644 E7904	SP000010411	BB644E7904HTSA1	SOD323	none			
BB 659C-02V H7902	SP000745108	BB659C02VH7902XTSA1	SC79	BB 659C-02V H7912	SP000745112	BB659C02VH7912XTSA1	SC79
BB 659C-02V H7908	SP000745110	BB659C02VH7908XTSA1	SC79	BB 659C-02V H7912	SP000745112	BB659C02VH7912XTSA1	SC79

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

PRODUCT DISCONTINUATION



PD_137_14

■ Last order:	2015-02-28
■ Last delivery:	2015-08-31

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	OPN	Package	Device	Ordering Code	OPN	Package
BB 664 02V H7902	SP000745118	BB66402VH7902XTSA1	SC79		none		
BB 669 E7904	SP000010419	BB669E7904HTSA1	SOD323		none		
BB 689-02V H7902	SP000745124	BB68902VH7902XTSA1	SC79		none		
BB 689-02V H7908	SP000745126	BB68902VH7908XTSA1	SC79		none		
BB 831 E7904	SP000012250	BB831E7904HTSA1	SOD323		none		
BF 2040R E6814	SP000012216	BF2040RE6814HTSA1	SOT143	BF 2040 E6814	SP000012215	BF2040E6814HTSA1	SOT143
BF 5030W H6327	SP000753488	BF5030WH6327XTSA1	SOT343		none		
BF 998R E6327	SP000010979	BF998RE6327HTSA1	SOT143	BF 998 E6327	SP000010978	BF998E6327HTSA1	SOT143
BF 999 E6433	SP000426300	BF999E6433HTMA1	SOT23	BF 999 E6327	SP000010985	BF999E6327HTSA1	SOT23
SD 197 E6552	SP000010382	SD197E6552HTSA1	SOD323		none		
ST 194 E6716	SP000010983	ST194E6716HTSA1	SOT143		none		

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!