



159 Ort Lane  
Merlin, OR, US 97532  
Phone: + 1 541 471 6256  
Fax: + 1 541 471 6251  
[www.linxtechnologies.com](http://www.linxtechnologies.com)

December 6, 2012

To: All customers using ANT-SKN-V1-1.50, ANT-SKN-V1-3.15 and ANT-SKN-V1-4.25 antenna skins

Re: End of life notice

Dear customer,

Linx Technologies is discontinuing production of the ANT-SKN-V1-1.50, ANT-SKN-V1-3.15 and ANT-SKN-V1-4.25 antenna skins.

We will continue to supply products to customers as stock allows. These parts are not recommended for new designs.

Parts may be scheduled for delivery up to six months after the last time buy date on a non-cancellable, non-refundable basis, depending on availability.

We are committed to working closely with our customers during this discontinuation. Please contact Linx if you have questions, concerns or would like more information.

## **End of Life Notice for ANT-SKN-V1-1.50, ANT-SKN-V1-3.15 and ANT-SKN-V1-4.25 Antenna Skins**

PCN #: LEOL-121206-11

Publish Date: December 6, 2012

### **Type of Change**

End of life

### **Products Affected**

- ANT-SKN-V1-1.50
- ANT-SKN-V1-3.15
- ANT-SKN-V1-4.25

### **Description of Change**

End of life notice for ANT-SKN-V1-1.50, ANT-SKN-V1-3.15 and ANT-SKN-V1-4.25

### **Reason for Change**

End of life

### **Effect of Change**

Production on the ANT-SKN-V1-1.50, ANT-SKN-V1-3.15 and ANT-SKN-V1-4.25 antenna skins will cease. We will continue to supply products to customers as stock allows. Parts may be scheduled for delivery up to six months after the last time buy date on a non-cancellable, non-refundable basis, depending on availability. The parts are not recommended for new designs.

There are currently no drop-in replacements for the ANT-SKN-V1-1.50, ANT-SKN-V1-3.15 and ANT-SKN-V1-4.25 antenna skins.

### **Anticipated Last Ship Date**

April 2013 or as stock allows

### **Qualification Data**

N/A

### **Last Time Buy Date**

No formal last time buy date is established