

Issue Date: September 21st, 2020

Dear Valued Customer,

This notice is to inform you of our efforts in re-sourcing a component used in a finished good that you have purchased from Littelfuse in the past.

Description of the Change:

- We will be changing the source of the stud used in the junction block JBPT5N01ZXB.

Reason for The Change:

- The current stud supplier, one who had supplied this component since before Littelfuse's acquisition of Cole Hersee, is one that no longer meets the production or commercial requirements to supply to Littelfuse.
- The proposed supplier of this component is one who already supplies similar products to Littelfuse today.

Effective Date of the Change:


- This will occur as a running change; shipments utilizing the new component are expected by end of Q1 2021.

What You Need to Do:

- No actions are required on your part. This vendor transition will not result in a change in fit, form, or function.

If you have any questions, please feel free to contact your Littelfuse Customer Service Representative or your Inside Sales Representative. We appreciate your business and our continued partnership.

Sincerely,



Zachary Naughton
Global Product Manager
Littelfuse Commercial Vehicle Products